



LTI3WOB

report date: 2024-03-28

General information

Make	MINI
Model	COOPER CLUBMAN
Colour	Blue
Year of manufacture	2013
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-03-19
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-14
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	10
Total items failed	6

MOT #14	2024-03-15 12:00
MOT test number	868335340839
Result	✓ Passed
Next expiry date	2025-03-14

MOT #13	2024-03-15 12:00
MOT test number	901391206803
Result	✗ Failed
<b>Pass with rectification</b>	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12	2023-03-13 17:24
MOT test number	671869440166
Result	✓ Passed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Minor</b>	Nearside Front Windscreen damaged but not adversely affecting driver's view Large chip (3.2 (a) (i))
<b>Advice</b>	Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #11** 2023-03-13 12:14**MOT test number** 449676290511**Result** ✗ Failed

**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view Large chip (3.2 (a) (i))

**Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively Wiper rubber split (3.4 (b) (ii))

**MOT #10** 2022-03-15 04:06**MOT test number** 918659564836**Result** ✓ Passed**MOT #9** 2021-09-07 10:54**MOT test number** 625285606150**Result** ✓ Passed**MOT #8** 2020-09-04 10:38**MOT test number** 715548571236**Result** ✓ Passed**MOT #7** 2020-09-03 14:35**MOT test number** 887340564988**Result** ✗ Failed

**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6** 2019-05-25 08:14**MOT test number** 823035531134**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #5** 2018-06-11 13:33**MOT test number** 220781439936**Result** ✓ Passed**MOT #4** 2017-06-14 13:16**MOT test number** 895961044314**Result** ✓ Passed**MOT #3** 2017-03-17 15:46**MOT test number** 816834367334**Result** ✓ Passed**MOT #2** 2017-03-16 12:54**MOT test number** 512377302459**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #1** 2016-03-01 15:38**MOT test number** 926758394498**Result** ✓ Passed**Advice** Front tyres worn inner and outer**Advice** Front tyres tread close to the limit



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
14 March 2025

Tax status	Valid until 1 May
Days left	368
MOT expiry date	14 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-23
Last registration	2024-03-15
Complete history	<a href="#">See info</a>



Registration #1	2013-03-23	14 mi
Registration #2	2016-03-01	36.523 mi
Registration #3	2017-03-16	51.705 mi
Registration #4	2017-03-17	51.705 mi
Registration #5	2017-06-14	51.748 mi
Registration #6	2018-06-11	53.909 mi
Registration #7	2019-05-25	56.311 mi
Registration #8	2020-09-03	60.256 mi
Registration #9	2021-05-20	61.277 mi
Registration #10	2021-05-20	61.277 mi
Registration #11	2021-05-20	61.277 mi
Registration #12	2021-05-20	61.277 mi
Registration #13	2021-05-20	61.277 mi
Registration #14	2021-05-20	61.277 mi
Registration #15	2021-05-20	61.277 mi
Registration #16	2021-05-20	61.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3937 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A414J448