



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Silver
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-11-09
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	4
Total items failed	2

MOT #10	2023-11-24 16:38
MOT test number	419893632773
Result	✓ Passed
Next expiry date	2024-12-04
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2022-12-05 16:35
MOT test number	882618151808
Result	✓ Passed

MOT #8	2022-12-02 16:10
MOT test number	622627388963
Result	✗ Failed
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #7	2021-09-28 12:52
MOT test number	478834064303
Result	✓ Passed

**MOT #6** 2020-10-07 11:22**MOT test number** 261569766691**Result** ✓ Passed**Advice** Nearside Rear slight movement in suspension**MOT #5** 2019-10-02 10:48**MOT test number** 956952934949**Result** ✓ Passed**MOT #4** 2018-08-15 14:49**MOT test number** 647379489340**Result** ✓ Passed**MOT #3** 2018-08-14 12:55**MOT test number** 207253560110**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #2** 2017-08-07 08:24**MOT test number** 443774613300**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**MOT #1** 2016-08-15 12:11**MOT test number** 818419800120**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 December 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YK63R XR
Plate since	2019-09-29
Current registration	YK63R XR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-06
Last registration	2023-11-24
Complete history	See info



Registration #1	2013-09-06	12 mi
Registration #2	2016-08-15	37.869 mi
Registration #3	2017-08-07	50.930 mi
Registration #4	2018-08-14	61.559 mi
Registration #5	2018-08-15	61.562 mi
Registration #6	2019-10-02	71.787 mi
Registration #7	2019-10-02	71.787 mi
Registration #8	2019-10-02	71.787 mi
Registration #9	2019-10-02	71.787 mi
Registration #10	2019-10-02	71.787 mi
Registration #11	2019-10-02	71.787 mi
Registration #12	2019-10-02	71.787 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1885 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1356895