





report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2009
Top speed	147 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-19

Pictures 23

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-09-09
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #13	2023-09-06 14:08
MOT test number	239297864947
Result	✓ Passed
Next expiry date	2024-09-09

MOT #12	2022-09-07	08:54
MOT test	number 56157833	9461
Result	√ P	assed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #11	2021-09-09 13:59
MOT test number	917236356480
Result	✓ Passed

MOT #10	2020-09-10 13:37
MOT test number	997968925981
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

WR59SLV

report date: 2024-03-28

Passed

MOT #9 2020-09-09 10:27

MOT test number 165288115131

Result X Failed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #8 2019-08-27 15:20

MOT test number 935552808162

Result ✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7 2018-09-10 09:26

MOT test number 783708631261

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6 2017-09-04 15:52

MOT test number 574453183952

Result ✓ Passed

MOT #5 2016-08-04 08:19

MOT test number 637463079917

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



WR59SLV report date: 2024-03-28

MOT #4 2015-09-01 11:02

MOT test number 826427823079

MOT #3 2015-03-09 12:26

MOT test number 847828265031

Result ✓ Passed

MOT #2 2014-03-13 12:21

MOT test number 125242074027

Result
✓ Passed

Notice Items removed from driver's view prior to test

MOT #1 2013-03-21 13:41

MOT test number 525320683044

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e union matery	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIE
Flate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-11-17
Last registration	2023-09-06
Complete history	See info



Registration #1	2009-11-17	12 mi
Registration #2	2013-03-21	14.779 mi
Registration #3	2014-03-13	22.636 mi
Registration #4	2015-03-09	28.555 mi
Registration #5	2015-09-01	32.559 mi
Registration #6	2016-08-04	35.839 mi
Registration #7	2017-09-04	38.982 mi
Registration #8	2018-09-10	42.514 mi
Registration #9		11.177 es
Registration #10		
Registration #10		77.777 es
Registration #11		11.777 es
-		11.77 m
Registration #11		11.777 ea 11.777 ea 11.777 ea
Registration #11 Registration #12		11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



WR59SLV report date: 2024-03-28

Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431245729

CarCheck.co.uk page 12/12