



report date: 2024-03-28

General information

| | |
|---------------------|---------------------|
| Make | MINI |
| Model | MINI (R58) COOPER D |
| Colour | Silver |
| Year of manufacture | 2012 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 112 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-10-12 |
| Pictures | 13 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-11 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-01 |
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 20 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #12 | 2023-10-17 07:55 |
| MOT test number | 411460262941 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-01 |

| | |
|-----------------|---|
| MOT #11 | 2022-11-02 12:40 |
| MOT test number | 711248768585 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Minor | Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|-----------------|------------------|
| MOT #10 | 2021-10-19 13:41 |
| MOT test number | 743606894401 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #9 | 2020-11-28 15:15 |
| MOT test number | 467302702917 |
| Result | ✓ Passed |

**MOT #8** 2019-11-23 11:53**MOT test number** 778611364726**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Covers and under-trays fitted**MOT #7** 2018-11-30 11:37**MOT test number** 356825276428**Result** ✓ Passed**Advice** Engine bay covers and under-trays fitted**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm, flat spots and nail in tread (5.2.3 (e))**Advice** Rear inner brake pads appear low**MOT #6** 2018-11-28 14:23**MOT test number** 770110938635**Result** ✗ Failed**Advice** Engine bay covers and under-trays fitted**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm, flat spots and nail in tread (5.2.3 (e))**Advice** Rear inner brake pads appear low**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5** 2017-11-28 12:35**MOT test number** 614772770128**Result** ✓ Passed**Advice** Covers fitted obscuring some components in the engine bay.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside rear tyre worn to 3mm tread depth and tread has flat spots.**MOT #4** 2017-11-28 10:21**MOT test number** 892805038162**Result** ✗ Failed**Advice** Covers fitted obscuring some components in the engine bay.**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside rear tyre worn to 3mm tread depth and tread has flat spots.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2016-12-02 12:54**MOT test number** 488811008918**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit has slight wear on inner edge (4.1.E.1)**MOT #2** 2016-02-08 10:56**MOT test number** 464807103984**Result** ✓ Passed**MOT #1** 2015-02-27 17:07**MOT test number** 266958955036**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 1 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BN62XYX |
| Plate since | 2019-09-28 |
| Current registration | BN62XYX |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2012-09-12 |
| Last registration | 2023-10-17 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-09-12 | 12 mi |
| Registration #2 | 2015-02-27 | 18.233 mi |
| Registration #3 | 2016-02-08 | 40.825 mi |
| Registration #4 | 2016-12-02 | 42.684 mi |
| Registration #5 | 2017-11-28 | 48.419 mi |
| Registration #6 | 2017-11-28 | 48.419 mi |
| Registration #7 | 2018-11-28 | 55.015 mi |
| Registration #8 | 2018-11-30 | 55.073 mi |
| Registration #9 | 2019-05-29 | 55.277 mi |
| Registration #10 | 2019-05-29 | 55.277 mi |
| Registration #11 | 2019-05-29 | 55.277 mi |
| Registration #12 | 2019-05-29 | 55.277 mi |
| Registration #13 | 2019-05-29 | 55.277 mi |
| Registration #14 | 2019-05-29 | 55.277 mi |
| Registration #15 | 2019-05-29 | 55.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1683 mm |
| Height | 1407 mm |
| Length | 3723 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1540 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 70817962 |