



Mercedes-Benz

CV08FNT

report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 109 CDI COMPACT P/V
Colour	Green
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



## Internet history

### Entry 3

Date	2021-12-03
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 2

Date	2021-10-10
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 1

Date	2021-10-09
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-28
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	41
Total items failed	12

MOT #21	2023-09-27 16:58
MOT test number	994454274761
Result	✓ Passed
Next expiry date	2024-09-28

MOT #20	2022-09-05 14:07
MOT test number	312038013430
Result	✓ Passed

MOT #19	2021-09-29 15:29
MOT test number	322272965802
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18	2021-02-15 11:17
MOT test number	865567181335
Result	✓ Passed
Advice	Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #17**

2021-02-15 09:05

**MOT test number**

289734226258

**Result****✗ Failed****Advice** Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Service brake binding but not excessively (1.2.1 (f))**MOT #16**

2020-02-12 16:13

**MOT test number**

106222339875

**Result****✓ Passed****Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #15**

2020-02-12 10:09

**MOT test number**

785975123625

**Result****✗ Failed****Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14** 2019-02-13 14:08**MOT test number** 475590881234**Result** ✓ Passed**MOT #13** 2019-02-11 15:08**MOT test number** 332571965261**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2018-03-16 13:59**MOT test number** 756322898680**Result** ✓ Passed**Advice** TYRES PERISHING**MOT #11** 2018-03-12 10:59**MOT test number** 997893353365**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded FROM BRAKE HOSE (3.6.B.2c)**Fail** Offside rear brake binding (3.7.B.1)**Advice** TYRES PERISHING**MOT #10** 2017-03-09 14:07**MOT test number** 901762131415**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #9** 2017-03-09 10:32**MOT test number** 235893073264**Result** ✗ Failed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Windscreen wiper does not clear the windscreen effectively Both (8.2.2)**MOT #8** 2016-02-23 15:10**MOT test number** 448897266806**Result** ✓ Passed**Advice** Offside front brake binding.**MOT #7** 2016-02-23 14:57**MOT test number** 608806156334**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside front brake binding.**MOT #6** 2015-03-04 11:47**MOT test number** 797383765090**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Passenger seat(s) missing at time of test**Advice** Offside Front Anti-roll bar synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5**

2015-02-26 15:21

**MOT test number**

386107655036

**Result**

✗ Failed

**Notice** Passenger seat(s) missing at time of test**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Headlamp aim too low and too far to the right. (1.8)**Advice** Offside Front Anti-roll bar synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4**

2014-02-25 14:46

**MOT test number**

556246354037

**Result**

✓ Passed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Passenger seat(s) missing at time of test**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2013-02-26 16:26

**MOT test number**

388077353097

**Result**

✓ Passed

**Notice** Lhf tyre worn on outer edge



MOT #2	2012-02-22 16:03
MOT test number	777093352005
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Nearside front tyre worn on outside edge.
Notice	Trailer brake light affected by another lamp.
Notice	Nail in nearside rear tyre

MOT #1	2011-02-23 16:51
MOT test number	597434151003
Result	✓ Passed
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)





Tax & MOT check

✕  
Untaxed

Tax expired:  
9 October 2023

✓  
MOT

Expires:  
28 September 2024

Tax status

Expired at 9 October 2023

Days left

203 days too late

MOT expiry date

28 September 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-03-01
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	15 mi
Registration #2	2011-02-23	34.490 mi
Registration #3	2012-02-22	41.218 mi
Registration #4	2013-02-26	48.337 mi
Registration #5	2014-02-25	55.833 mi
Registration #6	2015-02-26	62.796 mi
Registration #7	2015-03-04	62.991 mi
Registration #8	2016-02-23	68.876 mi
Registration #9	2016-02-23	68.876 mi
Registration #10	2017-03-09	75.635 mi
Registration #11	2017-03-09	75.635 mi
Registration #12	2018-03-12	77.019 mi
Registration #13	2018-03-16	77.028 mi
Registration #14	2019-03-20	78.377 mi
Registration #15	2019-03-20	78.377 mi
Registration #16	2019-03-20	78.377 mi
Registration #17	2019-03-20	78.377 mi
Registration #18	2019-03-20	78.377 mi
Registration #19	2019-03-20	78.377 mi
Registration #20	2019-03-20	78.377 mi
Registration #21	2019-03-20	78.377 mi
Registration #22	2019-03-20	78.377 mi
Registration #23	2019-03-20	78.377 mi
Registration #24	2019-03-20	78.377 mi
Registration #25	2019-03-20	78.377 mi



Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Engine number	64698051713889