






## General information

| Make Cl7               | TROEN          |
|------------------------|----------------|
| Model DS               | 53 DSTYLE PLUS |
| Colour Wh              | hite           |
| Year of manufacture 20 | 011            |
| Top speed 11           | .8 mph         |
| <b>0 - 60 mph</b> 9.9  | 9 seconds      |
| Gearbox 5 s            | speed Manual   |

## Engine & fuel consumption

| Power                   | 120 BHP             |
|-------------------------|---------------------|
| Max. torque             | 160 Nm at 4.200 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.1 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 40.4 mpg            |
| CO2 emission            | 138 g/km            |
| CO2 label               | E                   |







# Internet history

Entry 1

Date Pictures 2021-01-29

10

Listing price

View report



source: autoonline.co.uk



# MOT history

| MOT expiry date    | 2025-02-04 |
|--------------------|------------|
| MOT pass rate      | 79 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 3          |
| Total advice items | 20         |
| Total items failed | 4          |

| MOT #14                                                                                                          | 2024-02-05 16:18 |
|------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number                                                                                                  | 545966312151     |
| Result                                                                                                           | ✓ Passed         |
| Next expiry date                                                                                                 | 2025-02-04       |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))                                                         |                  |
| Advice Offside Rear Service brake binding but not excessively slight bind (1.2.1 (f))                            |                  |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))                                                        |                  |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3                                | 3 (d) (ii))      |



MOT #13

Result

**MOT test number** 

|                      | <b>MA61JNU</b><br>report date: 2024-03-29 |
|----------------------|-------------------------------------------|
|                      | 2024-02-03 14:20                          |
|                      | 845853746516<br>× Failed                  |
| e tested (4.1.2 (b)) |                                           |

| FailOffside Headlamp aim unable to be tested (4.1.2 (b))                                                         |
|------------------------------------------------------------------------------------------------------------------|
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))                                                        |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3 (d) (ii))                      |
| Advice Offside Rear Service brake binding but not excessively slight bind (1.2.1 (f))                            |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))                                                         |
| Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))                                  |

| MOT #12         | 2023-05-03 14:08 |
|-----------------|------------------|
| MOT test number | 498179733801     |
| Result          | ✓ Passed         |

| MOT #11  |                                                                                     | 2022-10-10 11:43 |
|----------|-------------------------------------------------------------------------------------|------------------|
| MOT test | number                                                                              | 155718934450     |
| Result   |                                                                                     | ✓ Passed         |
| Advice   | Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))             |                  |
| Advice   | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii | ))               |

| MOT #10                                                                                      |                                                                                     | 2022-10-10 11:43 |
|----------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------|
| MOT test                                                                                     | number                                                                              | 303676291164     |
| Result                                                                                       |                                                                                     | 🗙 Failed         |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))               |                                                                                     |                  |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |                                                                                     |                  |
| Pass wit                                                                                     | <b>h rectification</b> Windscreen washer provides insufficient washer liquid (3.5 ( | a))              |





| MOT #9   |                                                                                   | 2021-10-12 11:48 |
|----------|-----------------------------------------------------------------------------------|------------------|
| MOT test | number                                                                            | 325548799844     |
| Result   |                                                                                   | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))            |                  |
| MOT #8   |                                                                                   | 2020-10-06 10:15 |
| MOT test | number                                                                            | 730456361386     |
| Result   |                                                                                   | ✓ Passed         |
|          |                                                                                   |                  |
| MOT #7   |                                                                                   | 2019-10-07 08:28 |
| MOT test | number                                                                            | 923415030179     |
| Result   |                                                                                   | ✓ Passed         |
|          |                                                                                   |                  |
| MOT #6   |                                                                                   | 2018-10-09 08:14 |
| MOT test | number                                                                            | 944860810996     |
| Result   |                                                                                   | ✓ Passed         |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))             |                  |
| Advice   | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) ( | (ii))            |
| Advice   | Nearside Rear Nail in tyre                                                        |                  |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))              |                  |
| Advice   | Nearside Rear Child Seat fitted not allowing full inspection of adult belt        |                  |

| MOT #5          | 2017-10-10 08:35 |
|-----------------|------------------|
| MOT test number | 967308425903     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #4          | 2016-10-11 12:53 |
|-----------------|------------------|
| MOT test number | 432296287102     |
| Result          | ✓ Passed         |





| МОТ #3                  |                                                           | 2015-10-13 14:24 |
|-------------------------|-----------------------------------------------------------|------------------|
| MOT test number         |                                                           | 442057255510     |
| Result                  |                                                           | ✓ Passed         |
|                         |                                                           |                  |
| MOT #2                  |                                                           | 2014-10-10 14:51 |
| MOT test number         |                                                           | 886273084248     |
| Result                  |                                                           | ✓ Passed         |
|                         |                                                           |                  |
| MOT #1                  |                                                           | 2014-10-10 14:51 |
| MOT test number         |                                                           | 249683784205     |
| Result                  |                                                           | 🗙 Failed         |
| Pass with rectification | Offside Rear Rear position lamp(s) not working (1.1.A.3b) |                  |



Tax & MOT check

| √<br>Taxed                    | √<br>МОТ                           |
|-------------------------------|------------------------------------|
| <b>Tax due:</b><br>1 May 2024 | <b>Expires:</b><br>4 February 2025 |
| Tax status                    | Valid until 1 May                  |
| Days left                     | 3                                  |
| MOT expiry date               | 4 February 2025                    |
| Full MOT history              | See MOT history                    |

## Tax calculation

| Vehicle class                           | 48         |
|-----------------------------------------|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| 4   |
|-----|
| AMP |
|     |
|     |
| - A |
|     |
|     |
|     |
|     |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******                                                         |             |
|----------------------------------------------------------------|-------------|
| **********                                                     |             |
| *******                                                        |             |
| ******                                                         |             |
| **********                                                     |             |
| *******                                                        |             |
|                                                                | More info > |
| Plate changes                                                  |             |
| See in this check if this CITROEN had different number plates. |             |
| Number of plates                                               |             |
| Current registration                                           |             |
| Plate since                                                    |             |
| Current registration                                           |             |
| Plate since                                                    |             |
|                                                                |             |





### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2011-10-09 |
| Last registration          | 2024-02-05 |
| Complete history           | See info   |



| Registration #1  | 2011-10-09 | 28 mi      |
|------------------|------------|------------|
| Registration #2  | 2014-10-10 | 15.889 mi  |
| Registration #3  | 2015-10-13 | 19.254 mi  |
| Registration #4  | 2016-10-11 | 22.378 mi  |
| Registration #5  | 2017-10-10 | 25.747 mi  |
| Registration #6  | 2018-10-09 | 29.849 mi  |
| Registration #7  | 2019-10-07 | 33.573 mi  |
| Registration #8  | 2020-10-06 | 36.806 mi  |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 mi  |
| Registration #14 |            | 11.777 mi  |
| Registration #15 |            | 11.777 mi  |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 87%             |
| Children       | 71%             |
| Pedestrian     | 35%             |
| Safety systems | 83%             |
| Overall rating | 73%             |
| Video          | see crash video |



| Dimensions & weight                                    |                               |
|--------------------------------------------------------|-------------------------------|
| Width                                                  | 1715 mm                       |
| Height                                                 | 1483 mm                       |
| Length                                                 | 3948 mm                       |
| Wheel base                                             | 2464 mm                       |
| Kerb weight                                            | 1147 kg                       |
| Max. allowed weight                                    | 1554 kg                       |
|                                                        |                               |
| Additional information                                 |                               |
| Additional information Fuel tank capacity              | 48 I                          |
|                                                        | 48 l<br>Multi-Point Injection |
| Fuel tank capacity                                     |                               |
| Fuel tank capacity<br>Fuel delivery                    | Multi-Point Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Multi-Point Injection<br>3    |