





report date: 2024-03-28

## General information

Make	FIAT
Model	500 LOUNGE
Colour	Red
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-05-25

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2025-03-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	4
Total items failed	6

MOT #6	2024-03-15 10:13
MOT test number	924173706508
Result	✓ Passed
Next expiry date	2025-03-14

5	2024-03-14 11:11
MOT test number 420824899	
	<b>X</b> Failed
Windscreen washer not working (3.5 (a))	
Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Offside Front Obligatory mirror insecure (3.3 (b) (ii))	
	Windscreen washer not working (3.5 (a))  Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))  Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (i))  Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #4	2023-03-07 15:38
MOT test number	612735424280
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Offside Front Obligatory mirror slightly damaged glass cracked (3.3 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both lipped worn corroded (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2022-03-08 14:22

**MOT test number** 957065259534

MOT #2 2022-03-08 13:05

**MOT test number** 671591179480

Result X Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut worn cracked perished (5.2.3 (d) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing cracked perished (5.2.3 (d) (ii))

MOT #1 2021-01-11 12:16

**MOT test number** 981008813387

**Result** ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	14 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
************	
**************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-24
Last registration	2024-03-15
Complete history	See info



Registration #1	2018-04-24	17 mi
Registration #2	2021-01-11	20.610 mi
Registration #3		11.777 es
Registration #4	2022-03-08	26.033 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	***
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



## Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles2Engine number2380699