





report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC 110
Colour	Grey
Year of manufacture	2009
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-04

Pictures 12

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-19
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	9
Total items failed	11

MOT #18	2024-04-15 11:29
MOT test number	862020407221
Result	✓ Passed
Next expiry date	2025-04-19

MOT #17	2024-04-15 08:47	
MOT test number	485844446999	
Result	X Failed	
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.	2 (c))	

MOT #16	2023-04-19 13:46
MOT test number	909151217838
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #15 2023-04-19 11:46

MOT test number 388550800087

Result X Failed

Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)

(ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2022-04-12 08:22

MOT test number 441860062902

Advice Offside Rear Nail in tyre

MOT #13 2022-04-12 08:22

MOT test number 175121831968

Result X Failed

Advice Offside Rear Nail in tyre

Pass with rectification Windscreen washer not working (3.5 (a))

MOT #12 2021-04-20 08:58

MOT test number 614276107493

Advice Offside Front Tyre worn close to legal limit/worn on edge worn inner (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #11	2020-04-14 09:53
MOT test number	944172574074

MOT #10 2019-04-08 15:28

MOT test number 917460020753

Result ✓ Passed

MOT #9 2018-04-11 16:20

MOT test number 593642125951

Result ✓ Passed

MOT #8 2018-04-11 08:31

MOT test number 445562788542

Result X Failed

Fail Offside Rear fog lamp emits a light other than red lens broken (1.3.2e)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #7 2017-04-11 08:34

MOT test number 861473844430

MOT #6 2016-03-22 16:50

MOT test number 520081145046

Result ✓ Passed

MOT #5 2015-03-27 12:28

MOT test number 738686685038

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT #4 2014-04-01 17:49 245681194051 **MOT test number** Result ✓ Passed MOT #3 2014-03-31 09:53 **MOT test number** 155130194467 Result × Failed Nearside Rear Road wheel bead rim badly distorted (4.2.A.1a) Fail Fail Nearside Front Road wheel bead rim badly distorted (4.2.A.1a) Offside Front Road wheel bead rim badly distorted (4.2.A.1a) Fail

MOT #2 2013-04-16 13:49 378276903162 **MOT** test number Result ✓ Passed **MOT #1** 2013-04-12 11:30 **MOT test number** 119162103132 Result × Failed Fail Offside Front Road wheel distorted (4.2.A.1a) **Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



LF59XZA

report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-12-29
Last registration	2024-04-15
Complete history	See info



Registration #1	2009-12-29	23 mi
Registration #2	2013-04-12	17.126 mi
Registration #3	2013-04-16	17.126 mi
Registration #4	2014-03-31	21.379 mi
Registration #5	2014-04-01	21.379 mi
Registration #6	2015-03-27	25.670 mi
Registration #7	2016-03-22	29.360 mi
Registration #8	2017-04-11	34.132 mi
Registration #9	2018-04-11	37.771 mi
Registration #10	2018-04-11	37.775 mi
Registration #11		71.777 es
Registration #12		77.777 es
Registration #13		11.117 es
Registration #14		111,1177 ess
Registration #15		11.117 es
Registration #16		11.177 es
Registration #17		11.117 es
Registration #18		11.777 es
Registration #19		11.117 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	je 13/13

Number of axles 2

Engine number 9D82683