





report date: 2024-03-28

### General information

Make	FORD
Model	KUGA TITANIUM TDCI
Colour	Grey
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-06-09

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT #16

MOT expiry date	2024-08-11
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #17	2023-08-12 10:48
MOT test number	365539558481
Result	✓ Passed
Next expiry date	2024-08-11

MO1 #10		2022-00-12 13.31
MOT test	number	637587545220
Result		✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

2022-06-12 13-31

MOT #15	2021-06-14 12:14
MOT test number	393148732691
Result	✓ Passed
MOT #14	2021-03-15 13:38
MOT test number	713179841827
Result	✓ Passed
Advice Rear suspension arms and subframe corrosion but not to excess	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear suspension arms and subframe corrosion but not to excess

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12 2020-03-16 14:46

MOT test number 208882223548

Result Passed

MOT #11

MOT test number

288994853956

Result

Kearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10 2019-03-08 14:02

MOT test number 636795154286

Result ✓ Passed

MOT test number

732406470777

Result

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Front Upper Anti-roll bar linkage fractured ball joint broken (5.3.3 (b) (ii))

Fail Offside Front Headlamp levelling device inoperative linkage rod fractured / broken (4.1.5 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8		2018-03-09 15:53
<b>MOT test</b>	number	102609976761
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2017-03-18 12:03
MOT test number	794742437409
Result	✓ Passed
MOT #6	2017-03-11 12:37
MOT test number	813877084862
Result	<b>X</b> Failed
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #5	2016-03-17 10:24
MOT test number	777458285649
Result	<b>✓</b> Passed
MOT #4	2015-05-11 10:45
MOT test number	499341835192
Result	✓ Passed
MOT #3	2015-01-26 10:55
MOT test number	606006725091
Result	✓ Passed
Notice Rear tyres worn on inner shoulders	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2	2014-01-22 13:26
MOT test number	668462824060
Result	<b>✓</b> Passed
MOT #1	2013-01-16 10:52
MOT test number	379096913058

CarCheck.co.uk page 6/13



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	11 August 2024
Full MOT history	See MOT history

#### Tax calculation

W 11 1 1	40
Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\sim$	wner	hi	cto	-
$ \cup$	wner	ш	รเบ	IV

For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
**********	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	AIZ SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



EN59PTX report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-01-27
Last registration	2023-08-12
Complete history	See info



Registration #1	2010-01-27	17 mi
Registration #2	2013-01-16	35.558 mi
Registration #3	2014-01-22	47.318 mi
Registration #4	2015-01-26	60.606 mi
Registration #5	2015-05-11	63.122 mi
Registration #6	2016-03-17	68.783 mi
Registration #7	2017-03-11	72.434 mi
Registration #8	2017-03-18	72.451 mi
Registration #9	2018-03-09	75.399 mi
Registration #10	2019-03-01	78.737 mi
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		11.177 es
Registration #14		77.777 46
Registration #15		11.177 es
Registration #16		77.777 46
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D. 277 esc

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video

View the complete FORD factory list for this vehicle <u>here</u>.



More info >

# Dimensions & weight

Width	1842 mm
Height	1677 mm
Length	4443 mm
Kerb weight	1613 kg
Max. allowed weight	2130 kg

# Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

AS88158