





General information

Make	CITROEN
Model	C3 PICASSO BLUEHDI EDITION PICASSO
Colour	Silver
Year of manufacture	2016
Top speed	111 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	В





AP16XAJ report date: 2024-03-29

Internet history			
Entry 1			
Date	2022-02-1	1	
Pictures	5		
Listing price	View report		
	New Stock - Just In (01722) 622079 (Demonstrating Image Awaiting Image	<section-header><section-header><section-header><text><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></text></section-header></section-header></section-header>	We have a teses of bagens who work, way hard to make sure when the the most disaudak which is in part condition and at the test condition and test condition and test condition and the test condition and test

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-27
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	10
Total items failed	0

МОТ #6	2024-03-15 13:28
MOT test number	400897370583
Result	🗸 Passed
Next expiry date 2025-03-2	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #5	2023-03-28 14:58
MOT test number	658401712523
Result	✓ Passed

MOT #4	2022-03-23 16:31
MOT test number	290625883438
Result	✓ Passed
Advice Condensation nearside rear light	





MOT #3		2021-06-10 11:12
MOT test	number	332437209692
Result		✓ Passed
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cor	ds wall (5.2.3 (d) (i))
Advice	Nearside Outer sill damaged	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2020-07-09 10:38	
MOT test number	407490621922	
Result	✓ Passed	
Advice Nearside Front door and sill damaged		
Advice Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))		

MOT #1	2019-08-19 11:14
MOT test number	808431375744
Result	✓ Passed
Advice Nearside Front Outer sill damaged	



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	Expires: 27 March 2025	✓ МОТ
Tax status			Valid until 1 March
Days left			306
MOT expiry date			27 March 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		19	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	\$
Category	amp
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-08-23
Last registration	2024-03-15
Complete history	See info



Registration #1	2016-08-23	16 mi
Registration #2	2019-08-19	4.102 mi
Registration #3	2020-07-09	4.932 mi
Registration #4	2021-06-10	6.200 mi
Registration #5		11.117 mi
Registration #6		11.117 esi
Registration #7		11.777 esi
Registration #8		10.000 est

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight	
Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg
Additional information	
Additional information Fuel tank capacity	50 l
	50 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5