



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Red
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg







Internet history

Entry 1

Date	2021-09-29
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18

2023-07-20 09:28

MOT test number

274422777970

Result

✗ Failed

- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Nearside Front Windscreen wiper blade defective smearing (3.4 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Seats in boot folded
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Front Windscreen wiper blade defective smearing (3.4 (b) (i))
- MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #17

2022-07-20 11:14

MOT test number

128040343566

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

**MOT #16** 2021-07-09 10:08**MOT test number** 355695023299**Result** ✓ Passed**MOT #15** 2021-06-29 09:01**MOT test number** 125268203355**Result** ✗ Failed**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both in tread (5.2.3 (d) (ii))**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-07-20 08:36**MOT test number** 740772132267**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Front Service brake fluctuating, but not excessively BOTH SIDES (1.2.1 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13** 2019-05-17 14:10**MOT test number** 681442202973**Result** ✓ Passed

**MOT #12** 2018-05-10 13:28**MOT test number** 573272940115**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2017-05-09 10:12**MOT test number** 950389020840**Result** ✓ Passed**Advice** Nearside front tyre outer edge worn**Advice** Rear Child Seat fitted not allowing full inspection of adult belt All three seats**Advice** Offside front tyre inner edge worn**MOT #10** 2016-05-23 13:59**MOT test number** 181691356419**Result** ✓ Passed**MOT #9** 2016-05-23 13:59**MOT test number** 498793515766**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #8** 2015-05-21 09:43**MOT test number** 836001845199**Result** ✓ Passed**Notice** Offside front sidelight dim advice replace bulb**MOT #7** 2014-05-17 10:37**MOT test number** 187987434197**Result** ✓ Passed**Notice** Parking brake tested with engine stopped and ignition on**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-05-15 11:57**MOT test number** 539875734159**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #5** 2013-05-22 11:07**MOT test number** 396482843177**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #4** 2013-05-10 14:55**MOT test number** 686710333104**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Electronic parking brake control defective so that it cannot be satisfactorily operated (3.1.3c)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #3** 2012-05-28 15:37**MOT test number** 689089542120**Result** ✓ Passed**MOT #2** 2011-12-20 12:02**MOT test number** 528614051334**Result** ✓ Passed**Notice** Undertrays fitted**Notice** Front wiper blades slightly smearing**Notice** Front pads very low and discs lipped



MOT #1	2011-12-20 09:41
MOT test number	137094751339
Result	✗ Failed
Notice	Front wiper blades slightly smearing
Notice	Front pads very low and discs lipped
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Notice	Undertrays fitted



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	BD58MBY
Plate since	2024-03-28
Current registration	BD58MBY
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-12-31
Last registration	2023-07-20
Complete history	See info



Registration #1	2008-12-31	26 mi
Registration #2	2011-12-20	25.692 mi
Registration #3	2011-12-20	25.694 mi
Registration #4	2012-05-28	28.286 mi
Registration #5	2013-05-10	37.189 mi
Registration #6	2013-05-22	37.387 mi
Registration #7	2014-05-15	47.157 mi
Registration #8	2014-05-17	47.213 mi
Registration #9	2015-05-21	30.500 mi
Registration #10	2016-05-23	69.244 mi
Registration #11	2016-05-23	69.244 mi
Registration #12	2016-05-23	69.244 mi
Registration #13	2016-05-23	69.244 mi
Registration #14	2016-05-23	69.244 mi
Registration #15	2016-05-23	69.244 mi
Registration #16	2016-05-23	69.244 mi
Registration #17	2016-05-23	69.244 mi
Registration #18	2016-05-23	69.244 mi
Registration #19	2016-05-23	69.244 mi
Registration #20	2016-05-23	69.244 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0002257