





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 CRDI STYLE
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date	2021-08-01


Pictures 33

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-04
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-30
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	10
Total items failed	7

MOT #15	2023-08-14 09:31
MOT test number	559548771067
Result	✓ Passed
Next expiry date	2024-08-30
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2023-08-10 09:34
MOT test number	715944913135
Result	X Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Nail in tyre	

MOT #13	2022-08-23 15:15
MOT test number	808647160172
Result	✓ Passed
MOT #12	2022-08-23 08:19
MOT test number	230845374019
Result	× Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

CarCheck.co.uk page 3/12



Result

LT61RFZ report date: 2024-03-29

✓ Passed

MOT #11 2021-08-31 12:56

MOT test number 978502064665

Result ✓ Passed

MOT #10 2021-08-31 11:15

MOT test number 594025996382

Result × Failed

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #9 2020-09-19 09:20

MOT test number 871736129244

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8 2019-10-03 13:30

MOT test number 380964865100

Result

Passed

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7 2019-10-03 10:21

MOT test number 693137457038

Result X Failed

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



LT61RFZ

report date: 2024-03-29

MOT #6	2018-10-10 09:22
MOT test number	612429955434
Result	✓ Passed
MOT #5	2017-10-16 14:56
MOT test number	698194168824
Result	✓ Passed
MOT #4	2017-02-17 09:16
MOT test number	220480608954
Result	✓ Passed
MOT #3	2016-01-26 18:53
MOT test number	907444658139
Result	✓ Passed
MOT #2	2015-02-18 15:40
MOT test number	595359045041
Result	✓ Passed
MOT #1	2015-02-17 15:29
MOT test number	189538445081
Result	X Failed
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Nearside rear tyre deteriorated	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



LT61RFZ

report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· ·		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



71.777 mi

Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-01
Last registration	2023-08-14
Complete history	See info



Registration #1	2011-09-01	13 mi
Registration #2	2015-02-17	30.465 mi
Registration #3	2015-02-18	30.465 mi
Registration #4	2016-01-26	32.512 mi
Registration #5	2017-02-17	35.794 mi
Registration #6	2017-10-16	35.887 mi
Registration #7	2018-10-10	43.405 mi
Registration #8	2019-10-03	50.546 mi
Registration #9	2019-10-03	50.546 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

7070.70.70

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number D4FCBZ030124