



report date: 2024-03-29

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI EXCLUSIVE
Colour	Blue
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A





## Internet history

## Entry 3

Date	2022-02-23
Pictures	3
Listing price	<a href="#">View report</a>



source: yesauto.com

## Entry 2



Date	2022-02-20
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

## Entry 1

Date	2022-02-03
Pictures	11
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-01-12
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	19
Total items failed	5

## MOT #9 2024-01-13 15:32

MOT test number 642558840857

Result ✓ Passed

Next expiry date 2025-01-12

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge outer edge 205/55r17 (5.2.3 (e))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

## MOT #8 2024-01-13 11:13

MOT test number 547853088318

Result ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge outer edge 205/55r17 (5.2.3 (e))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Side repeater not working mirror indicator (4.4.1 (a) (ii))

## MOT #7 2022-12-29 15:14

MOT test number 971563321414

Result ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2022-01-13 16:33**MOT test number** 214404581722**Result** ✓ Passed**MOT #5** 2021-11-24 17:06**MOT test number** 443864925591**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (205/55R17) (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (205/55R17) (5.2.3 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**MOT #4** 2021-11-24 10:33**MOT test number** 295297117212**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (205/55R17) (5.2.3 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (205/55R17) (5.2.3 (e))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #3** 2020-12-05 12:23**MOT test number** 864025712489**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #2	2020-12-05 09:43
MOT test number	418800550119
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1	2019-12-02 16:07
MOT test number	342329344811
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
12 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	12 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>YJZ4361</b>
Plate since	2024-03-29
Current registration	<b>YJZ4361</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-04-13
Last registration	2024-01-13
Complete history	<a href="#">See info</a>



Registration #1	2016-04-13	7 mi
Registration #2	2019-12-02	21.528 mi
Registration #3	2020-12-05	32.697 mi
Registration #4	2020-12-05	32.697 mi
Registration #5	2021-11-24	41.081 mi
Registration #6	2021-11-24	41.082 mi
Registration #7	2022-01-13	42.259 mi
Registration #8	2022-01-13	42.259 mi
Registration #9	2022-01-13	42.259 mi
Registration #10	2022-01-13	42.259 mi
Registration #11	2022-01-13	42.259 mi
Registration #12	2022-01-13	42.259 mi
Registration #13	2022-01-13	42.259 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1826 mm
Height	1610 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBGY0067122