





General information

Make	MAZDA
Model	MX-5 I
Colour	Black
Year of manufacture	1999
Top speed	119 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	134 Nm at 5.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.9 mpg





Internet history	
Entry 1	
Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

	2024 05 20
MOT expiry date	2024-05-30
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	21
Total items failed	10

	2023-05-31 14:38
number	527127682440
	✓ Passed
ry date	2024-05-30
Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Underneath vehicle corroded	
Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
	ry date Nearside Front Service brake binding but not excessively (1.2.1 (f)) Underneath vehicle corroded Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))





MOT #22		2023-05-31 09:21
MOT test	number	221567219823
Result		🗙 Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail E	xhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2	2 (b))
Advice	Underneath vehicle corroded	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) ((ii))
Fail 0 (a) (i))	ffside Rear Seat belt anchorage prescribed area strength or continuity significant	ly reduced (7.1.1

MOT #3	21 2023-05-20 09:2
MOT te	st number 70611778766
Result	× Faile
Fail (a) (i))	Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail (a) (i))	Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1
Fail	Nearside Front Brakes imbalanced across an axle (1.2.1 (b) (i))

МОТ #20	2022-05-07 10:36
MOT test number	481448039333
Result	✓ Passed





MOT #19	2021-05-24 07:56
MOT #19 MOT test number	433665866986
Result	✓ Passed
MOT #18	2021-03-10 08:46
MOT test number	839937776760
Result	✓ Passed
MOT #17	2020-08-20 08:12
MOT test number	160453567940
Result	✓ Passed
MOT #16	2019-05-01 08:09
MOT test number	268085718346
Result	✓ Passed
MOT #15	2018-05-11 09:13
MOT test number	926324856939
Result	✓ Passed
MOT #14	2018-05-10 07:41
MOT test number	428130499459
Result	🗙 Failed
Fail Nearside Front Upper Suspension component mounting prescribed a (2.4.A.3)	rea is excessively corroded
MOT #13	2017-05-19 13:35

MOT #13	2017-05-19 13:35
MOT test number	192877013194
Result	✓ Passed





MOT #12	2017-05-19 12:37
MOT test number	605157168980
Result	🗙 Failed
Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.	.3.D.3)
Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)	
MOT #11	2016-06-14 14:40
MOT test number	783095381040
Result	✓ Passed
MOT #10	2016-06-13 14:05
MOT test number	180527818550
Result	🗙 Failed
Fail Nearside Lower Seat belt anchorage prescribed area is excessively corroded (5.2)	2.6)
MOT #9	2015-06-10 09:49
MOT test number	888331765137
Result	✓ Passed
MOT #8	2014-06-10 08:36
MOT test number	237341664105
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #7	2013-06-04 10:50
MOT test number	285965153156
Result	Passed
AdviceRear Brake pad(s) wearing thin (3.5.1g)NoticeRear silencer detrioratedAdviceFront Brake pad(s) wearing thin (3.5.1g)	
MOT #6	2012-05-25 08:52
MOT test number	787846742133
Result	✓ Passed

MOT #5	2011-01-05 10:47
MOT test number	735775501091
Result	✓ Passed

Front Brake pad(s) wearing thin (3.5.1g)

MOT #4	2009-12-29 15:33
MOT test number	992603769359
Result	✓ Passed
Advice Front brake disc slightly pitted (3.5.1h)	
MOT #3	2008-12-18 11:52
MOT test number	512923858331
Result	✓ Passed
MOT #2	2007-12-18 09:23

MOT test number	224092157387
Result	✓ Passed

Advice





MOT #1	2006-12-15 11:11
MOT test number	190299046358
Result	✓ Passed





Tax & MOT check







Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ARANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	*
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MAZDA had different number plates	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1999-12-31
Last registration	2023-05-31
Complete history	See info



Registration #1	1999-12-31	7 mi
Registration #2	2006-12-15	41.783 mi
Registration #3	2007-12-18	48.014 mi
Registration #4	2008-12-18	52.206 mi
Registration #5	2009-12-29	53.745 mi
Registration #6	2011-01-05	57.417 mi
Registration #7	2012-05-25	58.033 mi
Registration #8	2013-06-04	59.401 mi
Registration #9	2014-06-10	61.624 mi
Registration #10	2015-06-10	62.907 mi
Registration #11	2016-06-13	64.583 mi
Registration #12	2016-06-14	64.583 mi
Registration #13	2017-05-19	65.245 mi
Registration #14		11.777 est
Registration #15		11.222 esi
Registration #16		11.777 est
Registration #17		11.222 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.317 est
Registration #23		11.777 esi
Registration #24		11.777 est
Deviaturation #25		
Registration #25		





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1680 mm
Height	1225 mm
Length	3975 mm
Kerb weight	1015 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
	ζ