



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Red
Year of manufacture	2002
Top speed	133 mph
0 - 60 mph	8.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	229 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	30.7 mpg
CO2 emission	230 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-08-09
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-18
MOT pass rate	79 %
MOT passed	19
Failed MOT tests	5
Total advice items	26
Total items failed	16

MOT #24	2023-11-04 09:21
MOT test number	662522136726
Result	✓ Passed
Next expiry date	2024-11-18
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #23	2022-11-10 15:04
MOT test number	154473355003
Result	✓ Passed
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	UNDER TRAYS OBSCURING SOME ITEMS
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #22** 2022-11-10 12:27**MOT test number** 902562172347**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** UNDER TRAYS OBSCURING SOME ITEMS**Fail** Offside Front Hydraulic brake calliper inadequately mounted RETAINING CLIP NOT CORRECTLY FITTED (1.1.16 (c) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Direction indicator light intensity significantly reduced (4.4.3 (a))**Advice** BULB FAILURE LAMP ILLUMINATED**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #21** 2021-11-05 12:16**MOT test number** 783050875353**Result** ✓ Passed**MOT #20** 2020-11-19 11:54**MOT test number** 500225808752**Result** ✓ Passed**MOT #19** 2019-11-08 17:58**MOT test number** 360402836279**Result** ✓ Passed

**MOT #18** 2019-11-08 10:41**MOT test number** 196519894367**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #17** 2018-11-07 15:33**MOT test number** 354025244843**Result** ✓ Passed**MOT #16** 2017-11-07 10:33**MOT test number** 550730033402**Result** ✓ Passed**MOT #15** 2016-11-08 12:13**MOT test number** 143365076502**Result** ✓ Passed**Advice** Central exhaust box outer skin corroded**Advice** Front Items removed from driver's view prior to test**MOT #14** 2015-11-06 10:23**MOT test number** 796289838585**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2014-11-04 11:14**MOT test number** 298998404326**Result** ✓ Passed

**MOT #12** 2013-10-16 11:15**MOT test number** 605419883217**Result** ✓ Passed**Notice** Undertrays fitted at time of test.**MOT #11** 2012-11-05 10:31**MOT test number** 378270812381**Result** ✓ Passed**MOT #10** 2011-10-13 11:32**MOT test number** 775866781287**Result** ✓ Passed**MOT #9** 2011-10-12 15:07**MOT test number** 165105581206**Result** ✗ Failed**Fail** Nearside Headlamp aim too far to the right (1.8)**MOT #8** 2010-10-28 09:55**MOT test number** 361541200332**Result** ✓ Passed**MOT #7** 2009-11-06 16:18**MOT test number** 412030419332**Result** ✓ Passed

**MOT #6** 2009-11-06 10:57**MOT test number** 601480319309**Result** ✗ Failed**Notice** Brake pedal slightly spongy**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear position lamp(s) excessively damaged so that it is not visible from a reasonable distance (1.1.A.3d)**Notice** Nail in offside rear tyre**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2008-11-05 14:42**MOT test number** 154450518380**Result** ✓ Passed**MOT #4** 2007-10-31 11:08**MOT test number** 462724507449**Result** ✓ Passed**MOT #3** 2006-11-07 15:54**MOT test number** 584951116396**Result** ✓ Passed



MOT #2 2006-10-23 15:38

MOT test number 941406896229

Result		✗ Failed
Fail	Nearside Stop lamp remains on when the brakes are released (1.2.1e)	
Fail	Offside Stop lamp remains on when the brakes are released (1.2.1e)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Centre Stop lamp remains on when the brakes are released (1.2.1e)	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail	Offside Side repeater incomplete (1.5.A1b)	

MOT #1 2006-01-27 12:22

MOT test number 160577826417

Result ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
18 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	18 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>SV52ZTE</b>
Plate since	2024-03-29
Current registration	 <b>SV52ZTE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-11-19
Last registration	2023-11-04
Complete history	<a href="#">See info</a>



Registration #1	2002-11-19	21 mi
Registration #2	2006-01-27	25.956 mi
Registration #3	2006-10-23	27.702 mi
Registration #4	2006-11-07	27.718 mi
Registration #5	2007-10-31	33.679 mi
Registration #6	2008-11-05	38.866 mi
Registration #7	2009-11-06	45.160 mi
Registration #8	2009-11-06	45.166 mi
Registration #9	2010-10-28	50.042 mi
Registration #10	2011-10-12	53.476 mi
Registration #11	2011-10-13	53.480 mi
Registration #12	2012-11-05	55.829 mi
Registration #13	2013-10-16	56.992 mi
Registration #14	2014-10-16	58.337 mi
Registration #15	2015-10-16	59.682 mi
Registration #16	2016-10-16	61.027 mi
Registration #17	2017-10-16	62.372 mi
Registration #18	2018-10-16	63.717 mi
Registration #19	2019-10-16	65.062 mi
Registration #20	2020-10-16	66.407 mi
Registration #21	2021-10-16	67.752 mi
Registration #22	2022-10-16	69.097 mi
Registration #23	2023-10-16	70.442 mi
Registration #24	2024-10-16	71.787 mi
Registration #25	2025-10-16	73.132 mi
Registration #26	2026-10-16	74.477 mi

**More info** >



Dimensions & weight

Width	1715 mm
Height	1289 mm
Length	3995 mm
Wheel base	2400 mm
Kerb weight	1290 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11195832458569