



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 CODE
Colour	Black
Year of manufacture	2008
Top speed	126 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	143 Nm at 3.750 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	15
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-12-16
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	34
Total items failed	23

MOT #22 2023-12-12 11:21

MOT test number 360691596483

Result ✓ Passed

Next expiry date 2024-12-16

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #21 2022-11-22 13:02

MOT test number 528991484518

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #20**

2022-11-22 11:42

MOT test number

108972117390

Result**✗ Failed**

- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #19

2021-12-17 14:37

MOT test number

287292246842

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2021-12-14 13:23

MOT test number

102898078294

Result**✗ Failed****Fail** Rear Suspension component missing re bound/bump stops missing (5.3.3 (a) (ii))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #17**

2020-12-17 11:43

MOT test number

747651500199

Result**✓ Passed****MOT #16**

2020-01-06 14:54

MOT test number

453941388009

Result**✓ Passed****Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement most rear bush both sides (5.3.4 (a) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #15**

2020-01-06 12:59

MOT test number

866306358089

Result**✗ Failed****Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement most rear bush both sides (5.3.4 (a) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14** 2019-01-21 14:43**MOT test number** 183053914598**Result** ✓ Passed**MOT #13** 2019-01-21 09:12**MOT test number** 812884228557**Result** ✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Exhaust bracket broken

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2018-01-23 14:44**MOT test number** 671228207324**Result** ✓ Passed**MOT #11** 2018-01-23 09:35**MOT test number** 128720813086**Result** ✗ Failed

Fail Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #10 2017-01-04 10:35**MOT test number** 895783861207**Result** ✓ Passed

**MOT #9** 2016-01-30 11:59**MOT test number** 908966466460**Result** Passed**MOT #8** 2016-01-27 12:32**MOT test number** 280468661829**Result** Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front constant velocity joint is insecure (2.5.C.1b)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #7 2015-01-13 15:40**MOT test number** 306363715006**Result** Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-01-13 10:57**MOT test number** 646433715052**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front exhaust bracket broken**MOT #5** 2014-01-13 11:29**MOT test number** 316493414003**Result** ✓ Passed**MOT #4** 2014-01-13 11:02**MOT test number** 505103414050**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2013-01-14 15:37**MOT test number** 146284913420**Result** ✓ Passed



MOT #2	2013-01-11 10:10
MOT test number	955281413019
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Washers frozen
Fail	Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-12-09 12:12
MOT test number	619343741387
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 December 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	16 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YP58FUA
Plate since	2024-03-29
Current registration	YP58FUA
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-12-09
Last registration	2023-12-12
Complete history	See info



Registration #1	2008-12-09	27 mi
Registration #2	2011-12-09	25.302 mi
Registration #3	2013-01-11	35.827 mi
Registration #4	2013-01-14	35.830 mi
Registration #5	2014-01-13	50.336 mi
Registration #6	2014-01-13	20.336 mi
Registration #7	2015-01-13	58.831 mi
Registration #8	2015-01-13	58.831 mi
Registration #9	2016-01-27	59.036 mi
Registration #10	2016-01-30	59.038 mi
Registration #11	2017-01-04	63.550 mi
Registration #12	2018-01-23	66.504 mi
Registration #13	2018-01-23	66.506 mi
Registration #14	2019-01-23	66.507 mi
Registration #15	2019-01-23	66.507 mi
Registration #16	2019-01-23	66.507 mi
Registration #17	2019-01-23	66.507 mi
Registration #18	2019-01-23	66.507 mi
Registration #19	2019-01-23	66.507 mi
Registration #20	2019-01-23	66.507 mi
Registration #21	2019-01-23	66.507 mi
Registration #22	2019-01-23	66.507 mi
Registration #23	2019-01-23	66.507 mi
Registration #24	2019-01-23	66.507 mi
Registration #25	2019-01-23	66.507 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1084 kg
Max. allowed weight	1415 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FX7P3324893