





report date: 2024-03-29

General information

Make	FIAT
Model	500X MULTIJET CROSS PLUS
Colour	Black
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-28

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-02
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	22
Total items failed	7

MOT #7		2023-07-01 08:32
MOT test	number	733826233119
Result		✓ Passed
Next expi	ry date	2024-07-02
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply o	r cords (5.2.3 (d) (i))
Advice	Engine oil level low	
Advice	Front fog lights inop	

MOT #6		2023-07-01 08:32
MOT test r	number	300224196876
Result		× Failed
Pass wit	h rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Engine oil level low	
Advice	Front fog lights inop	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))

CarCheck.co.uk page 3/12



MOT #5 2022-07-01 14:16

MOT test number 748605763301

Result ✓ Passed

Advice Both front fog lights inop

Advice Tyre worn close to legal limit/worn on edge both rear wearing on edges (5.2.3 (e))

MOT #4 2022-07-01 12:06

MOT test number 219268514361

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut in tread (5.2.3 (d) (i))

Advice Engine oil on min

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Both front fog lights inop

Advice Items removed from driver's view prior to test

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut in tread (5.2.3 (d) (i))

Advice Tyre worn close to legal limit/worn on edge both front wearing on edges (5.2.3 (e))

Advice N/s/f day running light inop

MOT #3 2021-06-30 16:14

MOT test number 241327799343

Result ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2 2021-06-30 10:07

MOT test number 159521052169

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #1 2020-07-03 12:01

MOT test number 542075651557

Result ✓ Passed

Advice Nearside Front daytime running light not working

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is	

Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-28
Last registration	2023-07-01
Complete history	See info



Registration #1	2016-10-28	11 mi
Registration #2	2020-07-03	48.739 mi
Registration #3	2021-06-30	74.955 mi
Registration #4	2021-06-30	74.955 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number 7709347