



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 100 km/h	11.1 seconds
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-29
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-10
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	2

MOT #14	2023-07-11 09:39
MOT test number	589741529143
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Coil spring corroded Nearside & Offside (5.3.1 (b) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #13	2023-07-10 15:28
MOT test number	820525784863
Result	✗ Failed
Advice	Rear Coil spring corroded Nearside & Offside (5.3.1 (b) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12**

2022-06-22 13:58

MOT test number

949094801145

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inner Edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside Inner Face's (1.1.14 (a) (ii))**MOT #11**

2022-06-22 09:51

MOT test number

910004708865

Result

✗ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside Inner Face's (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner Edge (5.2.3 (e))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**MOT #10**

2021-07-06 10:39

MOT test number

719939877893

Result

✓ Passed

**MOT #9**

2021-06-29 09:05

MOT test number

763255352747

Result**✗ Failed****MAJOR** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Windscreen wiper blade defective n/s and o/s (3.4 (b) (i))**MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #8**

2020-08-18 13:46

MOT test number

810709859409

Result**✓ Passed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside non obligatory mirror glass cracked**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both sides rear suspension trailing arm front bushes (5.3.4 (a) (i))**MOT #7**

2020-08-18 12:11

MOT test number

100118003727

Result**✗ Failed****Advice** Suspension arm pin or bush worn but not resulting in excessive movement both sides rear suspension trailing arm front bushes (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #6**

2019-04-02 12:59

MOT test number

674631390328

Result**✓ Passed****Advice** Suspension arm pin or bush worn but not resulting in excessive movement rear trailing arm front bushes both sides perished (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-03-29 10:41**MOT test number** 236230790141**Result** ✓ Passed

Advice Nearside obligatory indirect vision device damaged, but not seriously affecting the rear view (8.1.2a)

MOT #4 2017-03-28 11:46**MOT test number** 490626677566**Result** ✓ Passed**MOT #3** 2017-03-24 11:24**MOT test number** 677923459273**Result** ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2016-03-16 11:21**MOT test number** 839477676414**Result** ✓ Passed**MOT #1** 2015-03-20 13:26**MOT test number** 435979575019**Result** ✓ Passed

Notice Reat tyres worn on inner edges and on limet now

Notice Front tyres wearing on inner edges



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WV12HHX
Plate since	2019-09-29
Current registration	WV12HHX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-04-02
Last registration	2023-07-11
Complete history	See info



Registration #1	2012-04-02	19 mi
Registration #2	2015-03-20	37.472 mi
Registration #3	2016-03-16	49.209 mi
Registration #4	2017-03-24	57.506 mi
Registration #5	2017-03-28	57.600 mi
Registration #6	2018-03-29	65.590 mi
Registration #7	2019-04-02	71.878 mi
Registration #8	2020-08-18	79.414 mi
Registration #9	2020-08-18	79.414 mi
Registration #10	2020-08-18	79.414 mi
Registration #11	2020-08-18	79.414 mi
Registration #12	2020-08-18	79.414 mi
Registration #13	2020-08-18	79.414 mi
Registration #14	2020-08-18	79.414 mi
Registration #15	2020-08-18	79.414 mi
Registration #16	2020-08-18	79.414 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number	BS48457
---------------	---------