



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 S D V50
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2


Date	2022-04-06
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-28
Pictures	1
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-05-08
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	2

MOT #15	2023-04-27 13:54
MOT test number	738452050110
Result	✓ Passed
Next expiry date	2024-05-08
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #14	2022-05-09 13:52
MOT test number	901755190991
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2021-03-14 13:49
MOT test number	260321567994
Result	✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Screen chip
Advice	Offside Front tyre poor condition cuts to tread + bold inner edge.

**MOT #12**

2020-03-16 16:57

MOT test number

729808101592

Result

✓ Passed

Advice Screen chip.**Advice** Offside rear +offside front tyres cuts in tread**Advice** Slight judder from nearside front brake disc.**MOT #11**

2020-03-16 15:43

MOT test number

490968268008

Result

✗ Failed

Advice Slight judder from nearside front brake disc.**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut in tread (5.2.3 (d) (i))**Advice** Screen chip.**Advice** Offside rear +offside front tyres cuts in tread**MOT #10**

2019-03-11 16:43

MOT test number

921867092499

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened n/s o/s (1.1.14 (a) (ii))**MOT #9**

2019-03-11 14:21

MOT test number

477317298149

Result

✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened n/s o/s (1.1.14 (a) (ii))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush excessive play. (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush excessive play. (5.3.4 (a) (i))

**MOT #8** 2018-03-15 10:38**MOT test number** 349208092492**Result** ✓ Passed**MOT #7** 2018-03-15 10:38**MOT test number** 151331082075**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #6** 2017-02-27 14:57**MOT test number** 142476738064**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-03-08 14:21**MOT test number** 869859449938**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-10-23 14:28**MOT test number** 828386894260**Result** ✓ Passed



MOT #3	2014-10-23 14:28
MOT test number	177076894274
Result	✗ Failed
Pass with rectification	Offside Rear Rear position lamp(s) not working (1.1.A.3b)

MOT #2	2013-10-30 15:49
MOT test number	235443403374
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-10-22 15:32
MOT test number	136676592241
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
8 May 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DE59XYW
Plate since	2019-03-29
Current registration	DE59XYW
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-06
Last registration	2023-04-27
Complete history	See info



Registration #1	2009-11-06	18 mi
Registration #2	2012-10-22	19.832 mi
Registration #3	2013-10-30	67.096 mi
Registration #4	2014-10-23	35.466 mi
Registration #5	2016-03-08	41.993 mi
Registration #6	2017-02-27	45.098 mi
Registration #7	2018-03-15	49.006 mi
Registration #8	2018-03-15	49.006 mi
Registration #9	2019-03-11	51.882 mi
Registration #10	2019-03-11	51.882 mi
Registration #11	2019-03-11	51.882 mi
Registration #12	2019-03-11	51.882 mi
Registration #13	2019-03-11	51.882 mi
Registration #14	2019-03-11	51.882 mi
Registration #15	2019-03-11	51.882 mi
Registration #16	2019-03-11	51.882 mi
Registration #17	2019-03-11	51.882 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	565929
---------------	--------