



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Red
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



**MOT history**

MOT expiry date	2023-11-20
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	8

MOT #16	2022-11-21 16:28
MOT test number	712052877834
Result	✓ Passed
Next expiry date	2023-11-20
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2021-11-05 11:11
MOT test number	922001772943
Result	✓ Passed
Advice	Slight play at steering arms
Advice	Slight corrosion to vehicle underside and exposed components

MOT #14	2020-11-18 15:37
MOT test number	328602751888
Result	✓ Passed
Advice	Nearside Front slightly stiff top strut bearing
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Slight dampness around steering rack
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2020-11-10 10:21

MOT test number

741299909516

Result**✗ Failed**

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Slight dampness around steering rack
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front slightly stiff top strut bearing

MOT #12

2019-11-14 15:30

MOT test number

805778605615

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2019-11-07 10:39

MOT test number

198345675552

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Suspension arm pin or bush likely to become detached trailing arm bush (5.3.4 (a) (ii))

**MOT #10** 2018-11-13 10:01**MOT test number** 715045901329**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear tyres wearing outer edges

MOT #9 2017-11-17 09:41**MOT test number** 858860663903**Result** ✓ Passed

Advice Offside Front Upper top strut bearing stiff

Advice Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #8 2017-11-09 10:30**MOT test number** 443201627997**Result** ✗ Failed

Fail Offside Front Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Rear Inner Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #7 2016-10-25 09:18**MOT test number** 885812259833**Result** ✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Slight play o/sf steering rack

Advice Slight dampness n/sf steering rack

**MOT #6** 2015-11-19 10:18**MOT test number** 318094111040**Result** ✓ Passed**MOT #5** 2015-11-18 14:42**MOT test number** 824368605266**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #4** 2015-04-28 14:51**MOT test number** 375838715146**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2014-05-06 11:31**MOT test number** 379136424111**Result** ✓ Passed**MOT #2** 2013-05-15 17:18**MOT test number** 686745933142**Result** ✓ Passed**MOT #1** 2012-06-23 13:01**MOT test number** 389015072102**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ09VUO
Plate since	2019-09-29
Current registration	EJ09VUO
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-06
Last registration	2022-11-21
Complete history	See info



Registration #1	2009-07-06	16 mi
Registration #2	2012-06-23	18.549 mi
Registration #3	2013-05-15	22.645 mi
Registration #4	2014-05-06	29.850 mi
Registration #5	2015-04-28	35.913 mi
Registration #6	2015-11-18	38.877 mi
Registration #7	2015-11-19	38.881 mi
Registration #8	2016-10-25	51.481 mi
Registration #9	2017-11-09	68.191 mi
Registration #10	2018-05-22	75.277 mi
Registration #11	2018-05-22	75.277 mi
Registration #12	2018-05-22	75.277 mi
Registration #13	2018-05-22	75.277 mi
Registration #14	2018-05-22	75.277 mi
Registration #15	2018-05-22	75.277 mi
Registration #16	2018-05-22	75.277 mi
Registration #17	2018-05-22	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192