





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	407 SPORT HDI
Colour	Black
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

## Internet history


#### Entry 1

Date 2021-07-28

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-03
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	13
Total items failed	12

MOT #19	2023-08-04 09:15
MOT test number	974686957216
Result	<b>✓</b> Passed
Next expiry date	2024-08-03

MOT #18		2022-07-18 15:55
MOT test	number	891515728321
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))	
Advice	Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Slight engine oil leak	

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #17** 2022-07-18 12:32 **MOT** test number 182929049158 Result × Failed Fail Offside Rear Brake hose excessively twisted (1.1.12 (b) (ii)) Fail Nearside Rear Brake hose excessively twisted (1.1.12 (b) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e)) **Advice** Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Slight engine oil leak

MOT #16

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #15
 2020-09-29 15:33

 MOT test number
 703657844358

 Result
 ✓ Passed

 MOT #14
 2020-09-29 10:08

 MOT test number
 671558641564

Result × Failed

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13 2019-05-17 08:17

**MOT test number** 583461769546

Result Passed

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

✓ Passed

MOT #12 2019-05-17 08:17

**MOT test number** 869789483790

Result X Failed

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2018-05-24 07:15

**MOT test number** 473308043482

**Result** ✓ Passed

**MOT #10** 2018-05-22 07:45

**MOT test number** 972763171106

**Result** X Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9** 2017-06-07 11:15

**MOT test number** 918874419821

Result \rightarrow Passed

**MOT #8** 2016-06-07 09:46

**MOT test number** 873996219190

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Result

CarCheck.co.uk page 5/14



report date: 2024-03-29

**MOT #7** 2016-06-07 09:46

**MOT test number** 800333010909

**Result** X Failed

**Pass with rectification** Nearside Front Front position lamp(s) not working side light (1.1.A.3b)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2015-06-15 12:01

**MOT test number** 536976665160

**Result** ✓ Passed

MOT #5 2015-06-15 12:01

**MOT test number** 159026465143

**Result** X Failed

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #4 2014-04-22 14:51

**MOT test number** 956892814196

**Result** ✓ Passed

MOT #3 2013-05-07 10:33

MOT test number 266117523122

**Notice** Offside rear tyre is worn slightly low and cracking on sidewall

**Notice** Nearside rear tyre worn slightly low and cracking on sidewall

CarCheck.co.uk page 6/14



EF08WLE report date: 2024-03-29

MOT #2 2012-05-22 08:53
MOT test number 219233442431

MOT #1 2011-06-14 11:27

**MOT test number** 618605761105

**Result** 
✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	3 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

$\Omega_{M/1}$	aar	hic	ton
Owi	ıeı	1115	ισιν

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		TC
************		
manus .		
***************************************		
	More info >	
	Piore inito	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



EFO8WLE report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-24
Last registration	2023-08-04
Complete history	See info



Registration #1	2008-06-24	10 mi
Registration #2	2011-06-14	13.151 mi
Registration #3	2012-05-22	23.282 mi
Registration #4	2013-05-07	33.879 mi
Registration #5	2014-04-22	45.609 mi
Registration #6	2015-06-15	55.371 mi
Registration #7	2016-06-07	63.656 mi
Registration #8	2016-06-07	63.656 mi
Registration #9	2017-06-07	70.409 mi
Registration #10	2018-05-22	76.413 mi
Registration #11		9.70 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		71.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Max. allowed weight	1950 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 14/14

**Engine number** 

DYUK4096137