





report date: 2024-03-29

### General information

Make	MAZDA
Model	MX-5 I ROADSTER SPORT BLACK
Colour	Multi-colour
Year of manufacture	2012
Top speed	136 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	158 BHP
Max. torque	188 Nm at 5.000 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/12



### Internet history

### Entry 1

Date 2021-02-01

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-19
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #11	2023-05-20 12:19
MOT test number	670749823099
Result	✓ Passed
Next expiry date	2024-05-19

MOT #10		2022-05-13 15:21
MOT test	number	199178191118
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2021-05-20 07:41
MOT test number	469621287168
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #8 2021-03-31 08:04

**MOT test number** 341217992648

**Result** X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #7 2020-03-19 10:00

**MOT test number** 817464963185

Result \sqrt{Passed}

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2019-03-22 10:45

**MOT test number** 836400956191

**Result** ✓ Passed

MOT #5 2018-03-22 11:10

**MOT test number** 855964624531

Result \rightarrow Passed

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Advice** Offside Rear Nail in tyre

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #4 2017-03-24 11:02

**MOT test number** 892318193477

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



 MOT #3
 2016-03-14 13:08

 MOT test number
 241251185418

**Result** 
✓ Passed

MOT #2 2016-03-14 09:53

**MOT test number** 737588874557

Result X Failed

**Fail** Nearside Front Tyre has ply or cords exposed side wall damage (4.1.D.1b)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2015-03-09 09:22

**MOT test number** 779098065078

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	19 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-12
Last registration	2023-05-20
Complete history	See info



Registration #1	2012-03-12	24 mi
Registration #2	2015-03-09	33.402 mi
Registration #3	2016-03-14	44.144 mi
Registration #4	2016-03-14	44.144 mi
Registration #5	2017-03-24	56.329 mi
Registration #6	2018-03-22	66.189 mi
Registration #7	2019-03-22	74.822 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		70,777 mg

More info >

CarCheck.co.uk page 11/12



### Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1173 kg
Max. allowed weight	1375 kg

### Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 20410082

CarCheck.co.uk page 12/12