



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Silver
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-22
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #13	2023-09-27 13:54
MOT test number	252248298286
Result	✓ Passed
Next expiry date	2024-09-27
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2022-09-23 13:04
MOT test number	299552006206
Result	✓ Passed

MOT #11	2021-09-28 08:17
MOT test number	274299271656
Result	✓ Passed

MOT #10	2021-09-27 16:09
MOT test number	660235407573
Result	✗ Failed
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #9** 2020-12-17 11:15**MOT test number** 751643575502**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear, rear section from flexi-hose (1.1.11 (c))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear, rear section from flexi-hose (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2019-12-19 16:19**MOT test number** 184937155076**Result** ✓ Passed**MOT #7** 2019-12-18 09:40**MOT test number** 915534418769**Result** ✗ Failed**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #6** 2018-12-21 09:20**MOT test number** 544902796947**Result** ✓ Passed**Advice** Under trays & covers are fitted, not allowing full inspection of some components**MOT #5** 2017-12-21 09:47**MOT test number** 984256579238**Result** ✓ Passed**Advice** Carried out emission test, no result**Advice** Under trays & covers are fitted, not allowing full inspection of some components

**MOT #4** 2017-12-21 09:47**MOT test number** 614306232513**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Under trays & covers are fitted, not allowing full inspection of some components**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Carried out emission test, no result**MOT #3** 2016-12-12 12:32**MOT test number** 914951048692**Result** ✓ Passed**MOT #2** 2015-12-17 12:04**MOT test number** 276961160316**Result** ✓ Passed**Advice** Nearside Front tyre 3mm**MOT #1** 2015-12-17 10:22**MOT test number** 710595346280**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)**Advice** Nearside Front tyre 3mm



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
27 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	27 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>BD62YRY</b>
Plate since	2019-09-29
Current registration	<b>BD62YRY</b>
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-03
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2013-01-03	29 mi
Registration #2	2015-12-17	56.507 mi
Registration #3	2015-12-17	56.507 mi
Registration #4	2016-12-12	70.054 mi
Registration #5	2017-12-21	76.167 mi
Registration #6	2017-12-21	76.167 mi
Registration #7	2018-12-21	81.538 mi
Registration #8	2019-12-18	86.086 mi
Registration #9	2020-09-29	91.277 mi
Registration #10	2021-09-29	96.468 mi
Registration #11	2022-09-29	101.659 mi
Registration #12	2023-09-27	106.850 mi
Registration #13	2023-09-27	106.850 mi
Registration #14	2023-09-27	106.850 mi
Registration #15	2023-09-27	106.850 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDCU263340