



TOYOTA

KJ5ILSE


report date: 2024-03-28

General information

Make	TOYOTA
Model	MR2 ROADSTER
Colour	Silver
Year of manufacture	2001
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-08
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-04
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	40
Total items failed	17

MOT #24	2022-07-01 10:01
MOT test number	220197236826
Result	✓ Passed
Next expiry date	2023-07-04
Advice	Steering column universal joint has slight wear or play (2.2.2 (c))

MOT #23	2022-06-30 11:07
MOT test number	948788112550
Result	✗ Failed
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Advice	Steering column universal joint has slight wear or play (2.2.2 (c))

MOT #22	2021-07-05 15:44
MOT test number	802128591132
Result	✓ Passed
Advice	Underseal on suspension components making it difficult to inspect bushes

MOT #21	2020-04-23 13:57
MOT test number	200586738520
Result	✓ Passed

**MOT #20** 2018-11-30 12:03**MOT test number** 504564277604**Result** ✓ Passed**Advice** Under trays fitted**MOT #19** 2018-11-30 09:18**MOT test number** 985842148278**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Under trays fitted**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #18** 2017-09-01 08:07**MOT test number** 399567821499**Result** ✓ Passed**MOT #17** 2017-09-01 08:07**MOT test number** 727369941220**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #16 2016-08-09 13:08

MOT test number 386435158337

Result ✓ Passed

- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #15 2016-08-05 08:38

MOT test number 278869163642

Result ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)



MOT #14

2015-08-06 14:17

MOT test number

173259957891

Result		✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front coil spring corroded (2.4.C.1b)	
Advice	Under covers fitted not allowing full inspection under side and front compartment.	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front coil spring corroded (2.4.C.1b)	
Advice	O/S & N/S/F Stay bars corroded.	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

**MOT #13**

2015-07-30 12:39

MOT test number

207818595533

Result**✗ Failed****Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** O/S & N/S/F Stay bars corroded.**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Fail** Offside front brake binding (3.7.B.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Under covers fitted not allowing full inspection under side and front compartment.**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Front coil spring corroded (2.4.C.1b)**MOT #12**

2014-07-18 19:06

MOT test number

485329594164

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #11** 2014-07-18 13:54**MOT test number** 616729494172**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #10** 2013-06-06 09:54**MOT test number** 126727253126**Result** ✓ Passed**MOT #9** 2012-05-19 12:16**MOT test number** 966800642135**Result** ✓ Passed**MOT #8** 2012-05-18 12:26**MOT test number** 207579632423**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #7** 2011-05-23 09:45**MOT test number** 497143141156**Result** ✓ Passed



MOT #6	2010-09-06 11:35
MOT test number	570509540298
Result	✓ Passed
MOT #5	2009-08-13 09:42
MOT test number	680965929220
Result	✓ Passed
MOT #4	2008-08-21 15:00
MOT test number	321184838200
Result	✓ Passed
MOT #3	2007-08-31 13:56
MOT test number	942903847257
Result	✓ Passed
MOT #2	2006-08-30 12:24
MOT test number	751202546240
Result	✓ Passed
MOT #1	2005-08-23 09:40
MOT test number	393455335428
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KJ51LSE
Plate since	2019-09-28
Current registration	KJ51LSE
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-09-01
Last registration	2022-07-01
Complete history	See info



Registration #1	2001-09-01	21 mi
Registration #2	2005-08-23	30.163 mi
Registration #3	2006-08-30	37.949 mi
Registration #4	2007-08-31	47.254 mi
Registration #5	2008-08-21	54.972 mi
Registration #6	2009-08-13	62.527 mi
Registration #7	2010-09-06	65.550 mi
Registration #8	2011-05-23	65.875 mi
Registration #9	2012-05-18	70.284 mi
Registration #10	2012-05-19	70.287 mi
Registration #11	2013-06-06	71.400 mi
Registration #12	2014-07-18	84.620 mi
Registration #13	2014-07-18	84.620 mi
Registration #14	2015-05-20	95.377 mi
Registration #15	2015-05-20	95.377 mi
Registration #16	2015-05-20	95.377 mi
Registration #17	2015-05-20	95.377 mi
Registration #18	2015-05-20	95.377 mi
Registration #19	2015-05-20	95.377 mi
Registration #20	2015-05-20	95.377 mi
Registration #21	2015-05-20	95.377 mi
Registration #22	2015-05-20	95.377 mi
Registration #23	2015-05-20	95.377 mi
Registration #24	2015-05-20	95.377 mi
Registration #25	2015-05-20	95.377 mi
Registration #26	2015-05-20	95.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1240 mm
Length	3885 mm
Wheel base	2450 mm
Kerb weight	960 kg
Max. allowed weight	1225 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1ZZ0702143