





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | I800 CRDI SE |
| Colour | Silver |
| Year of manufacture | 2017 |
| Top speed | 112 mph |
| 0 - 60 mph | 14.4 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 168 BHP |
|-------------------------|---------------------|
| Max. torque | 440 Nm at 2.000 rpm |
| Engine capacity | 2.497 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 25.2 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 32.1 mpg |
| CO2 emission | 225 g/km |
| CO2 label | K |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

| _ | | • | | _ | - |
|---|---|---|----|---|---|
| - | n | т | rv | , | |
| | | | | | |

| Lifety 1 | |
|---------------|-------------|
| Date | 2021-12-23 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| | _ | | | |
|----|---|-----|----|-----|
| MO | 1 | hic | to | r\/ |
| | | | | ıv. |
| | | | | . , |

| MOT expiry date | 2025-01-09 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #6 | | 2023-12-21 16:13 |
|-----------|---|------------------|
| MOT test | number | 551941105854 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-09 |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #5 | 2022-12-16 11:37 |
|-----------------|------------------|
| MOT test number | 723282421803 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2022-01-10 14:55 |
| MOT test number | 724749036435 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2021-08-17 12:40 |

| MOT #3 | 2021-08-17 12:40 |
|-----------------|------------------|
| MOT test number | 873446242341 |
| Result | √ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Headlamp aim too high and too far to the right. (4.1.2 (a))

Pass with rectification

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 9 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|--------------|
| Band | K |
| First licence fee (12 months) | £ 1.565,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 2.220,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



EX670BD report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|-------------|
| | |
| manus . | |
| | |
| *************************************** | |
| | |
| manuse and the same and the sam | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-09-01 |
| Last registration | 2023-12-21 |
| Complete history | See info |



| Registration #1 | 2017-09-01 | 23 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-08-28 | 26.372 mi |
| Registration #3 | 2021-08-17 | 30.563 mi |
| Registration #4 | 2021-08-17 | 30.563 mi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 80% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| Width | 1920 mm |
|---------------------|---------|
| Height | 1925 mm |
| Length | 5125 mm |
| Wheel base | 3200 mm |
| Kerb weight | 2248 kg |
| Max. allowed weight | 3070 kg |

Additional information

| Fuel tank capacity | 75 I | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 8 | age 11/11 |

Number of axles 2

Engine number D4CBG180998