



PEUGEOT




report date: 2024-10-07

General information

| | |
|---------------------|------------------------------------|
| Make | PEUGEOT |
| Model | AUTOHAUS BLUE HDI S/S TEPEE ALLURE |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 106 mph |
| Gearbox | 5 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 100 BHP |
| Max. torque | 254 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 65.7 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 109 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|----------|------------|
| Date | 2023-12-14 |
| Pictures | 8 |



source: [g3remarketing.co.uk](https://www.g3remarketing.co.uk)



MOT history

| | |
|---------------------------|------------|
| MOT expiry date | 2022-10-30 |
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| | |
|-------------------------|---|
| MOT #3 | 2021-10-12 10:24 |
| MOT test number | 321746701520 |
| Result | ✓ Passed |
| Next expiry date | 2022-10-30 |
| Advice | Rear rear seat belts not tested. seats are folded down for wheel chair use. |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |

| | |
|------------------------|------------------|
| MOT #2 | 2020-10-27 14:58 |
| MOT test number | 755557737843 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #1 | 2019-10-31 12:57 |
| MOT test number | 365931260401 |
| Result | ✓ Passed |



Tax & MOT check

×
Untaxed

Tax expired:
30 March 2022

×
MOT

Expired:
30 October 2022

Tax status Expired at 30 March 2022

Days left 955 days too late

MOT expiry date 30 October 2022

Full MOT history [See MOT history](#)

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|------------------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|-------|-----|
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | SF66HCJ |
| Plate since | 2019-09-29 |
| Current registration | SF66HCJ |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


| | |
|--------------------------|----------|
| Finance company | REDACTED |
| Date of agreement | REDACTED |
| Agreement type | REDACTED |
| Agreement term | REDACTED |
| Agreement number | REDACTED |
| Contact info | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 4 |
| First mileage registration | 2017-01-09 |
| Last registration | 2021-10-12 |
| Complete history | See info |



| | | |
|-----------------|------------|----------|
| Registration #1 | 2017-01-09 | 13 mi |
| Registration #2 | 2019-10-31 | 3,485 mi |
| Registration #3 | 2021-10-12 | 3,500 mi |
| Registration #4 | 2024-10-07 | 3,513 mi |

[More info >](#)



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 73% |
| Children | 78% |
| Pedestrian | 48% |
| Safety systems | 86% |
| Overall rating | 70% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1862 mm |
| Length | 4384 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1383 kg |
| Max. allowed weight | 2075 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Number of axles

2

Engine number

JBHU3020834