



Ti250VG

report date: 2024-03-29

General information

Make	LOTUS
Model	ELISE
Colour	Silver
Year of manufacture	1999
Top speed	126 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	165 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-29
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	11
Total items failed	14

MOT #20	2023-09-26 16:10
MOT test number	268021711826
Result	✓ Passed
Next expiry date	2024-10-12

MOT #19	2022-10-13 16:02
MOT test number	175006128460
Result	✓ Passed

MOT #18	2022-10-06 11:14
MOT test number	392623068124
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Rear fog lamp not working (4.5.1 (a) (ii))

MOT #17	2021-10-12 10:11
MOT test number	881212011189
Result	✓ Passed



MOT #16	2020-09-29 12:31
MOT test number	303382266139
Result	✓ Passed
Advice	Nearside Play in steering rack inner joint(s)

MOT #15	2020-09-28 09:15
MOT test number	220994477761
Result	✗ Failed
Advice	Nearside Play in steering rack inner joint(s)
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Stop lamp(s) all not working (4.3.1 (a) (iii))
Fail	Nearside Headlamp aim too high (4.1.2 (a))

MOT #14	2019-09-25 10:35
MOT test number	855817338541
Result	✓ Passed

MOT #13	2019-09-23 09:30
MOT test number	821677975404
Result	✗ Failed
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Fail	Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Headlamp aim too high (4.1.2 (a))

**MOT #12**

2018-10-01 11:42

MOT test number

981263476170

Result

✓ Passed

Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2018-04-13 08:36

MOT test number

163027065451

Result

✓ Passed

Advice

Nearside Front Inner Play in steering rack inner joint(s)

Advice

All 4 tyres aged

MOT #10

2017-05-15 10:26

MOT test number

336798007030

Result

✓ Passed

MOT #9

2017-05-09 13:28

MOT test number

308605514620

Result

✗ Failed

Fail

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Fail

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice

Offside Headlamp has a product on the lens but not seriously reducing light output condensation (1.7.5a)

**MOT #8** 2016-04-07 10:07**MOT test number** 325395894064**Result** ✓ Passed**MOT #7** 2015-02-10 10:27**MOT test number** 119711245430**Result** ✓ Passed**MOT #6** 2010-06-16 16:57**MOT test number** 291367060417**Result** ✓ Passed**MOT #5** 2010-06-16 15:27**MOT test number** 794817660116**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #4** 2009-05-11 14:24**MOT test number** 782101539174**Result** ✓ Passed**MOT #3** 2008-05-10 11:40**MOT test number** 892331938161**Result** ✓ Passed**MOT #2** 2007-01-19 10:18**MOT test number** 120849217486**Result** ✓ Passed



MOT #1	2006-09-26 10:28
MOT test number	403249566238
Result	✓ Passed
Advice	Nearside Front Ball joint has slight play (2.2.B.1f)



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
12 October 2024

Tax status		Valid until 1 December
Days left		215
MOT expiry date		12 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LOTUS. See if, where and when this LOTUS had damage and the car repair costs. We also check if this LOTUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LOTUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LOTUS? How many owners did this LOTUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this LOTUS had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this LOTUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LOTUS has been settled.

If not, and you buy this LOTUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LOTUS is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1999-12-31
Last registration	2023-09-26
Complete history	See info



Registration #1	1999-12-31	12 mi
Registration #2	2006-09-26	47.458 mi
Registration #3	2007-01-19	47.887 mi
Registration #4	2008-05-10	53.394 mi
Registration #5	2009-05-11	54.419 mi
Registration #6	2010-06-16	55.164 mi
Registration #7	2010-06-16	55.173 mi
Registration #8	2015-02-10	56.707 mi
Registration #9	2016-04-07	57.059 mi
Registration #10	2017-05-09	57.195 mi
Registration #11	2017-05-15	57.199 mi
Registration #12	2019-05-20	58.227 mi
Registration #13	2019-05-20	58.227 mi
Registration #14	2019-05-20	58.227 mi
Registration #15	2019-05-20	58.227 mi
Registration #16	2019-05-20	58.227 mi
Registration #17	2019-05-20	58.227 mi
Registration #18	2019-05-20	58.227 mi
Registration #19	2019-05-20	58.227 mi
Registration #20	2019-05-20	58.227 mi
Registration #21	2019-05-20	58.227 mi
Registration #22	2019-05-20	58.227 mi

More info >



Dimensions & weight

Width	1719 mm
Height	1143 mm
Length	3728 mm
Wheel base	2300 mm
Kerb weight	750 kg

Additional information

Fuel tank capacity	40 l
Number of doors	2
Number of axles	2
Engine number	18K4FJ31237862