



report date: 2024-03-29

General information

| | |
|---------------------|------------------|
| Make | HONDA |
| Model | ACCORD I-DTEC EX |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 132 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 2.000 rpm |
| Engine capacity | 2.199 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 157 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-03 |
| Pictures | 25 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-11 |
| MOT pass rate | 86 % |
| MOT passed | 12 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #14 | 2023-07-12 15:20 |
| MOT test number | 356628557164 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-11 |
| Advice | Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |
| Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |

| | |
|-----------------|------------------|
| MOT #13 | 2022-05-13 09:31 |
| MOT test number | 684711319657 |
| Result | ✓ Passed |

| | |
|-----------------|------------------------------|
| MOT #12 | 2021-01-06 16:24 |
| MOT test number | 413940659591 |
| Result | ✓ Passed |
| Advice | O/s/r tyre worn center tread |

**MOT #11** 2021-01-05 11:39**MOT test number** 597007453983**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** O/s/r tyre worn center tread**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #10** 2020-01-20 09:36**MOT test number** 797044649815**Result** ✓ Passed**Advice** Exhaust system has surface corrosion**MOT #9** 2018-12-20 14:06**MOT test number** 554334877226**Result** ✓ Passed**MOT #8** 2018-01-03 10:17**MOT test number** 845912037182**Result** ✓ Passed**Advice** Nearside Front fog light lens cracked**MOT #7** 2017-01-05 14:46**MOT test number** 555883774653**Result** ✓ Passed**MOT #6** 2016-02-19 16:51**MOT test number** 147169341532**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #5 | 2016-02-18 16:27 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 808388323467 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

| | |
|---------------|-----------------------------------|
| Advice | Offside Rear slight bind on wheel |
|---------------|-----------------------------------|

| | |
|-------------|---|
| Fail | Rear brake application uneven (3.7.B.2) |
|-------------|---|

| | |
|---------------|------------------|
| MOT #4 | 2015-01-19 16:47 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 119099015045 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2014-06-13 09:26 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 165054964130 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2013-06-19 09:22 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 559040373174 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #1 | 2012-09-04 16:35 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 175858342298 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 11 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HONDA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2009-09-01 |
| Last registration | 2023-07-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-09-01 | 25 mi |
| Registration #2 | 2012-09-04 | 22.022 mi |
| Registration #3 | 2013-06-19 | 26.435 mi |
| Registration #4 | 2014-06-13 | 43.124 mi |
| Registration #5 | 2015-01-19 | 55.287 mi |
| Registration #6 | 2016-02-18 | 64.673 mi |
| Registration #7 | 2016-02-19 | 64.826 mi |
| Registration #8 | 2017-01-05 | 71.859 mi |
| Registration #9 | 2018-05-20 | 75.377 mi |
| Registration #10 | 2019-05-20 | 75.377 mi |
| Registration #11 | 2020-05-20 | 75.377 mi |
| Registration #12 | 2021-05-20 | 75.377 mi |
| Registration #13 | 2022-05-20 | 75.377 mi |
| Registration #14 | 2023-05-20 | 75.377 mi |
| Registration #15 | 2023-05-20 | 75.377 mi |
| Registration #16 | 2023-05-20 | 75.377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 86% |
| Children | 79% |
| Pedestrian | 54% |
| Safety systems | 86% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 1840 mm |
| Height | 1440 mm |
| Length | 4740 mm |
| Wheel base | 2705 mm |
| Kerb weight | 1559 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 65 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | N22B11106400 |