





report date: 2024-03-29

General information

Make	VAUXHALL
Model	CASCADA ELITE CDTI
Colour	White
Year of manufacture	2013
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	165 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.956 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/11



YS13HSF report date: 2024-03-29

MOT history

MOT expiry date	2025-01-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #10		2023-12-29 14:17
MOT test	number	999843585406
Result		✓ Passed
Next expi	ry date	2025-01-01
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #9	2023-12-29 14:08
MOT test number	951945926257
Result	X Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Service brake efficiency below requirements (1.2.2 (a) (i))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #8	2022-12-15 13:49
MOT test number	229706651598
Result	✓ Passed

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #7 2022-12-15 13:49

MOT test number 423575399630

Result X Failed

Pass with rectification Windscree

Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6 2021-12-22 14:34

MOT test number 306101116678

Result ✓ Passed

MOT #5 2020-12-12 11:20

MOT test number 580749231706

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Brake pad(s) wearing thin front & rear (1.1.13 (a) (ii))

MOT #4 2019-06-22 09:58

MOT test number 788157484288

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-07-02 13:36

MOT test number 512565241643

Result

Passed

Advice Fitted with engine covers/under trays

MOT #2 2017-06-23 10:39

MOT test number 361335590661

Result

Passed

Advice Rear tyres slight cracking

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1

MOT test number

Result

Advice Fitted with engine cover and under tray

CarCheck.co.uk page 4/11



YS13HSF report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	1 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29


Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

Owner history		
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.		-

	More info	>
Plate changes		
See in this check if this VAUXHALL had different number plates.		
Number of plates		,
Current registration	UK ZIS	
Plate since		
Current registration	NK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-27
Last registration	2023-12-29
Complete history	See info



B	2012.06.27	6
Registration #1	2013-06-27	6 mi
Registration #2	2016-06-23	17.357 mi
Registration #3	2017-06-23	21.523 mi
Registration #4	2018-07-02	26.707 mi
Registration #5	2019-06-22	34.036 mi
Registration #6	2020-12-12	44.176 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		10.707 es

More info >

CarCheck.co.uk page 10/11



YS13HSF report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1741 kg
Max. allowed weight	2215 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A20DTH -17A96036LBS

CarCheck.co.uk page 11/11