



PEUGEOT



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | PEUGEOT        |
| Model               | 107 ACCESS     |
| Colour              | White          |
| Year of manufacture | 2012           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 14.2 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                    |
|-------------------------|--------------------|
| Power                   | 68 BHP             |
| Max. torque             | 93 Nm at 3.600 rpm |
| Engine capacity         | 998 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 55.4 mpg           |
| Consumption extra urban | 74.3 mpg           |
| Consumption combined    | 65.7 mpg           |
| CO2 emission            | 99 g/km            |
| CO2 label               | A                  |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-03                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-25 |
| MOT pass rate      | 92 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 1          |
| Total advice items | 16         |
| Total items failed | 0          |

## MOT #12 2024-03-29 12:38

MOT test number 923374902667

Result ✓ Passed

Next expiry date 2025-04-25

- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #11 2023-04-13 10:35

MOT test number 317606863217

Result ✓ Passed

- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2022-04-13 08:05**MOT test number** 456412966333**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2021-04-26 17:43**MOT test number** 563378806086**Result** ✓ Passed**MOT #8** 2021-04-26 16:43**MOT test number** 163062466457**Result** ✗ Failed

**MAJOR** Offside Rear Direction indicator not working (4.4.1 (a) (ii))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #7** 2020-10-27 09:33**MOT test number** 659227046898**Result** ✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Items removed from driver's view prior to test

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 0.4mm useable tread remaining (5.2.3 (e))

**MOT #6** 2019-11-29 17:34**MOT test number** 191011060894**Result** ✓ Passed



|               |                  |
|---------------|------------------|
| <b>MOT #5</b> | 2019-04-25 14:26 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 989254614109 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                           |
|---------------|---------------------------|
| <b>Advice</b> | Offside Rear Nail in tyre |
|---------------|---------------------------|

|               |                  |
|---------------|------------------|
| <b>MOT #4</b> | 2018-04-26 09:06 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 486823392285 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                                |
|---------------|--------------------------------|
| <b>Advice</b> | Front brake discs are corroded |
|---------------|--------------------------------|

|               |                  |
|---------------|------------------|
| <b>MOT #3</b> | 2017-04-05 15:24 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 603054931085 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #2</b> | 2016-04-09 13:20 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 287973054539 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|

|               |                  |
|---------------|------------------|
| <b>MOT #1</b> | 2015-04-17 14:54 |
|---------------|------------------|

|                        |              |
|------------------------|--------------|
| <b>MOT test number</b> | 467757005119 |
|------------------------|--------------|

|               |          |
|---------------|----------|
| <b>Result</b> | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
25 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 306                             |
| <b>MOT expiry date</b>  | 25 April 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 48             |
| <b>Band</b>                                    | A              |
| <b>Single payment (12 months)</b>              | £ 0,00,-       |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | Not applicable |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>PK12AVO</b> |
| Plate since          | 2019-03-29     |
| Current registration | <b>PK12AVO</b> |
| Plate since          | 2019-03-29     |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2012-04-26               |
| Last registration          | 2024-03-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-04-26 | 25 mi     |
| Registration #2  | 2015-04-17 | 21.436 mi |
| Registration #3  | 2016-04-09 | 26.854 mi |
| Registration #4  | 2017-04-05 | 35.115 mi |
| Registration #5  | 2018-04-26 | 45.518 mi |
| Registration #6  | 2019-04-25 | 49.712 mi |
| Registration #7  | 2019-11-29 | 49.990 mi |
| Registration #8  | 2020-05-20 | 50.277 mi |
| Registration #9  | 2020-05-20 | 50.277 mi |
| Registration #10 | 2020-05-20 | 50.277 mi |
| Registration #11 | 2020-05-20 | 50.277 mi |
| Registration #12 | 2020-05-20 | 50.277 mi |
| Registration #13 | 2020-05-20 | 50.277 mi |
| Registration #14 | 2020-05-20 | 50.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1630 mm |
| Height              | 1465 mm |
| Length              | 3430 mm |
| Wheel base          | 2340 mm |
| Kerb weight         | 900 kg  |
| Max. allowed weight | 1180 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |
| Number of axles    | 2                     |
| Engine number      | 7155098               |