



RENAULT

**HYI4SCZ**

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A





## Internet history

### Entry 3

Date	2021-12-13
Pictures	2
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 2

Date	2021-10-07
Pictures	2
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 1

Date	2021-08-11
Pictures	2
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2025-04-01
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	20
Total items failed	8

MOT #14	2024-04-02 13:29
MOT test number	265693882982
Result	✓ Passed
Next expiry date	2025-04-01
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2023-03-11 12:11
MOT test number	136232674545
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #12	2022-03-07 14:56
MOT test number	472017084579
Result	✓ Passed
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Engine and under covers fitted obscuring some components

**MOT #11**

2022-02-28 18:19

**MOT test number**

549487185953

**Result****✗ Failed****Minor**

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Advice**

Engine and under covers fitted obscuring some components

**MAJOR**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #10**

2021-03-10 13:57

**MOT test number**

681811901115

**Result****✓ Passed****Advice**

Rear Outer Brake pipe corroded, covered in grease or other material Nearside and offside (1.1.11 (c))

**MOT #9**

2021-03-05 16:59

**MOT test number**

708919928964

**Result****✗ Failed****MAJOR**

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR**

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MAJOR**

Nearside Rear Bumper insecure (6.1.4 (a) (i))

**MAJOR**

Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice**

Rear Outer Brake pipe corroded, covered in grease or other material Nearside and offside (1.1.11 (c))

**MOT #8**

2020-02-29 12:14

**MOT test number**

257512854490

**Result****✓ Passed**

**MOT #7** 2020-02-28 13:44**MOT test number** 263654686963**Result** ✗ Failed**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front day running light not working**DANGEROUS** Body component likely to become detached rear bumper crash damage (6.2.1 (a) (ii))**MAJOR** Towbar component excessively damaged (6.1.6 (a))**MOT #6** 2019-03-06 14:14**MOT test number** 490790807710**Result** ✓ Passed**MOT #5** 2019-03-06 14:14**MOT test number** 811564120143**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #4** 2018-02-15 15:49**MOT test number** 609193930305**Result** ✓ Passed**MOT #3** 2018-02-14 14:10**MOT test number** 875313441253**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #2	2017-02-28 14:52
MOT test number	391395616324
Result	✓ Passed

MOT #1	2017-02-28 14:04
MOT test number	526140046613
Result	✗ Failed
<div><div>Fail</div>Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)</div>	
<div><div>Fail</div>Front Brakes imbalanced across an axle (3.7.B.5b)</div>	
<div><div>Fail</div>Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)</div>	
<div><div>Fail</div>Service brake: efficiency below requirements (3.7.B.7)</div>	



Tax & MOT check

X

Untaxed

Tax expired:  
1 March 2024

✓

MOT

Expires:  
1 April 2025

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	1 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>REDACTED</b>
Plate since	2019-01-01
Current registration	<b>REDACTED</b>
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2014-03-07
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2014-03-07	18 mi
Registration #2	2017-02-28	43.487 mi
Registration #3	2017-02-28	43.490 mi
Registration #4	2018-02-14	56.152 mi
Registration #5	2018-02-15	56.155 mi
Registration #6	2019-03-06	67.893 mi
Registration #7	2019-03-06	67.893 mi
Registration #8	2020-02-28	77.887 mi
Registration #9	2020-02-29	77.889 mi
Registration #10	2020-03-01	77.891 mi
Registration #11	2020-03-02	77.893 mi
Registration #12	2020-03-03	77.895 mi
Registration #13	2020-03-04	77.897 mi
Registration #14	2020-03-05	77.899 mi
Registration #15	2020-03-06	77.901 mi
Registration #16	2020-03-07	77.903 mi
Registration #17	2020-03-08	77.905 mi
Registration #18	2020-03-09	77.907 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D292824