



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 SE ECOFLEX
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-11-04
Pictures	6
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-10-20
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	33
Total items failed	11

MOT #16	2024-01-12 15:56
MOT test number	873576680235
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, but not excessively near and offside (1.1.14 (a) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2024-01-11 15:18

MOT test number

331646845891

Result**✗ Failed**

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, but not excessively near and offside (1.1.14 (a) (i))

MOT #14

2022-09-26 11:43

MOT test number

678157010049

Result**✓ Passed**

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13

2021-10-05 09:17

MOT test number

226008626358

Result**✓ Passed****MOT #12**

2020-11-26 11:37

MOT test number

311117147125

Result**✓ Passed**

**MOT #11**

2020-11-23 17:22

MOT test number

353521050848

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge close to exposing cords. (5.2.3 (e))**MOT #10**

2019-11-22 13:42

MOT test number

653592782197

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both corroded/worn on inside faces. (1.1.14 (a) (ii))**MOT #9**

2019-11-22 13:42

MOT test number

982542340115

Result

✗ Failed

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both corroded/worn on inside faces. (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #8**

2018-10-09 13:13

MOT test number

690524906272

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases box corroded (6.1.2 (a))

**MOT #7** 2018-10-08 16:03**MOT test number** 253102515930**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases box corroded (6.1.2 (a))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2017-10-05 16:17**MOT test number** 147623395923**Result** ✓ Passed**Advice** Advise offside rear indicator faded**MOT #5** 2017-10-04 13:03**MOT test number** 515095280340**Result** ✗ Failed**Advice** Advise offside rear indicator faded**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Both rear tyres perished**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2016-10-11 10:48**MOT test number** 188154160871**Result** ✓ Passed**MOT #3** 2015-10-08 14:28**MOT test number** 216389690437**Result** ✓ Passed



MOT #2 2014-10-07 10:03

MOT test number 439060484204

Result ✓ Passed

Advice Centre Front Parking brake lever has little reserve travel (3.1.6b)

Notice Advise off side back side pannel dented

Notice Advise drivers door handle as wear in otter release

Notice Advise both front tyres wearing inner edgers

MOT #1 2014-10-06 16:59

MOT test number 378789874427

Result ✗ Failed

Notice Advise off side back side pannel dented

Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Advise drivers door handle as wear in otter release

Notice Advise both front tyres wearing inner edgers

Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Centre Front Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 January 2025

Tax status		Valid until 1 April
Days left		337
MOT expiry date		11 January 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YR61SBZ
Plate since	2024-03-28
Current registration	YR61SBZ
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-09-30
Last registration	2024-01-12
Complete history	See info



Registration #1	2011-09-30	28 mi
Registration #2	2014-10-06	41.905 mi
Registration #3	2014-10-07	41.905 mi
Registration #4	2015-10-08	48.990 mi
Registration #5	2016-10-11	59.972 mi
Registration #6	2017-10-04	69.642 mi
Registration #7	2017-10-05	69.642 mi
Registration #8	2018-10-08	77.852 mi
Registration #9	2018-10-09	77.852 mi
Registration #10	2019-11-22	82.499 mi
Registration #11	2019-10-20	85.277 mi
Registration #12	2019-10-20	85.277 mi
Registration #13	2019-10-20	85.277 mi
Registration #14	2019-10-20	85.277 mi
Registration #15	2019-10-20	85.277 mi
Registration #16	2019-10-20	85.277 mi
Registration #17	2019-10-20	85.277 mi
Registration #18	2019-10-20	85.277 mi
Registration #19	2019-10-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4322 mm
Wheel base	2716 mm
Kerb weight	1233 kg
Max. allowed weight	1805 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	4285434