



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 DDIS
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-03-28
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #12 2020-03-02 12:02

MOT test number 328927070310

Result ✓ Passed

Next expiry date 2021-03-28

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Handbrake lever travel is high but not effecting parking brake performance

MOT #11 2019-03-21 10:11

MOT test number 292173418463

Result ✓ Passed

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Rear axle corroded

**MOT #10** 2019-03-18 14:02**MOT test number** 213138028730**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear axle corroded**MOT #9** 2018-03-27 11:49**MOT test number** 536044194312**Result** ✓ Passed**MOT #8** 2017-03-28 07:03**MOT test number** 872690686279**Result** ✓ Passed**MOT #7** 2017-03-15 13:46**MOT test number** 995763073265**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2016-03-18 10:39**MOT test number** 975842007026**Result** ✓ Passed**Advice** Advise wiper blade offside**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-03-20 10:27**MOT test number** 605569475061**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-03-21 09:58**MOT test number** 117140384089**Result** ✓ Passed**MOT #3** 2013-03-21 15:37**MOT test number** 205700483074**Result** ✓ Passed**MOT #2** 2012-03-27 13:35**MOT test number** 148147382408**Result** ✓ Passed**MOT #1** 2011-03-17 12:03**MOT test number** 627926271080**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
8 February 2021

X

MOT

Expired:
28 March 2021

Tax status	Expired at 8 February 2021
Days left	1175 days too late
MOT expiry date	28 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-03-28
Last registration	2020-03-02
Complete history	See info



Registration #1	2008-03-28	29 mi
Registration #2	2011-03-17	31.480 mi
Registration #3	2012-03-27	46.248 mi
Registration #4	2013-03-21	59.190 mi
Registration #5	2014-03-21	71.347 mi
Registration #6	2015-03-20	82.257 mi
Registration #7	2016-03-18	87.658 mi
Registration #8	2016-03-18	87.658 mi
Registration #9	2016-03-18	87.658 mi
Registration #10	2016-03-18	87.658 mi
Registration #11	2016-03-18	87.658 mi
Registration #12	2016-03-18	87.658 mi
Registration #13	2016-03-18	87.658 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1300 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	10JBAX0000870