





report date: 2024-03-28

#### General information

Make	BMW
Model	430 430D M SPORT GRAN COUPE
Colour	Blue
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/10



## Internet history

#### Entry 2

Date	2021-10-08	
Pictures	0	
Listing price	<u>View report</u>	

#### source: cargurus.co.uk

#### Entry 1

Date	2021-10-07	
Pictures	34	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-02-22
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #8	2024-02-23 16:21
MOT test number	358417122111
Result	✓ Passed
Next expiry date	2025-02-22

MOT #7	2023-01-13 15:41
MOT test number	714493788753
Result	<b>✓</b> Passed

MOT #6	2021-10-12 11:20
MOT test number	567638117013
Result	✓ Passed

MOT #5	2021-10-12 11:00

MOT test number 182843867478

Result X Failed

Fail Nearside Direction indicator not working wing mirror indicator not working. (4.4.1 (a) (ii))

CarCheck.co.uk page 3/10



MOT #4 2020-09-11 16:21

**MOT test number** 744069813480

**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Oil leak, but not excessive Rear Differential (8.4.1 (a) (i))

MOT #3 2019-09-28 11:16

**MOT test number** 340193216777

Result \( \sqrt{Passed} \)

MOT #2 2019-09-27 15:10

**MOT test number** 194652390818

**Result** X Failed

**Advice** Both front tyres are worn on edges

**Advice** Offside Front Play in steering rack inner joint(s)

Fail Front Position lamp not working (4.2.1 (a) (ii))

MOT #1 2018-09-01 08:43

MOT test number 223943877698

**Result** 
✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e when miscory		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-01
Last registration	2024-02-23
Complete history	See info



Registration #1	2015-09-01	23 mi
Registration #2	2018-09-01	13.354 mi
Registration #3	2019-09-27	15.826 mi
Registration #4	2019-09-28	15.832 mi
Registration #5	2020-09-11	31.668 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 9/10



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



## Dimensions & weight

Width	1825 mm
Height	1397 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1605 kg
Max. allowed weight	2165 kg

# Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10,

Number of axles 2

**Engine number** 59119323