



NLIIEVN

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ-L
Colour	Silver
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	145 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-30
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	12

MOT #13	2023-06-27 10:57
MOT test number	313352718261
Result	✓ Passed
Next expiry date	2024-06-30

MOT #12	2023-06-26 10:08
MOT test number	433237773489
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11	2022-07-01 12:47
MOT test number	812356165845
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2022-07-01 09:35

MOT test number

134996420949

Result**✗ Failed****Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Horn not working (7.7 (a))**MOT #9**

2021-03-25 16:35

MOT test number

987067857124

Result**✓ Passed****MOT #8**

2020-02-14 10:24

MOT test number

944617680182

Result**✓ Passed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Handbrake adjustment**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7** 2019-03-13 12:00**MOT test number** 902215037544**Result** ✓ Passed

Advice Suspension arm pin or bush worn but not resulting in excessive movement n/s/f and o/s/f (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake pipe corroded, covered in grease or other material n/s/f, o/s/f, o/s inner main. (1.1.11 (c))

MOT #6 2019-03-08 15:23**MOT test number** 291059747765**Result** ✗ Failed

Fail Brake pedal anti-slip provision missing (1.1.2 (c))

Advice Brake pipe corroded, covered in grease or other material n/s/f, o/s/f, o/s inner main. (1.1.11 (c))

Fail Brake pipe excessively corroded n/s/r and o/s/r (1.1.11 (c))

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))

Fail Offside Outer Brake pipe excessively corroded main (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement n/s/f and o/s/f (5.3.4 (a) (i))

MOT #5 2018-03-09 16:21**MOT test number** 542928970088**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2017-03-08 08:14**MOT test number** 169734786627**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2016-03-18 17:21**MOT test number** 181370491224**Result** ✓ Passed**MOT #2** 2015-02-26 16:59**MOT test number** 509327755007**Result** ✓ Passed**MOT #1** 2014-02-24 16:45**MOT test number** 507875954035**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
17 January 2024

✓

MOT

Expires:
30 June 2024

Tax status	Expired at 17 January 2024
Days left	102 days too late
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-01
Last registration	2023-06-27
Complete history	See info



Registration #1	2011-03-01	19 mi
Registration #2	2014-02-24	13.956 mi
Registration #3	2015-02-26	18.746 mi
Registration #4	2016-03-18	24.024 mi
Registration #5	2017-03-08	28.712 mi
Registration #6	2018-03-09	43.527 mi
Registration #7	2019-03-08	57.038 mi
Registration #8	2019-03-13	57.124 mi
Registration #9	2019-03-20	57.124 mi
Registration #10	2019-03-27	57.124 mi
Registration #11	2019-04-03	57.124 mi
Registration #12	2019-04-10	57.124 mi
Registration #13	2019-04-17	57.124 mi
Registration #14	2019-04-24	57.124 mi
Registration #15	2019-05-01	57.124 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1565 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1140 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1522760