



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE
Colour	Blue
Year of manufacture	-
Top speed	89 mph
0 - 60 mph	19.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	120 Nm at 2.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	47.9 mpg
Consumption combined	41.5 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-12-22
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-21
Pictures	22
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2021-12-22 10:46
MOT test number	831489070109
Result	✓ Passed
Next expiry date	2023-01-21

MOT #17	2021-01-22 16:40
MOT test number	765202493932
Result	✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Rear fog lamp lens defective which has no effect on emitted light lens broken (4.5.1 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #16

2021-01-22 11:00

MOT test number

773656836205

Result

✗ Failed

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Offside Rear fog lamp lens defective which has no effect on emitted light lens broken (4.5.1 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2019-05-11 11:27

MOT test number

636486251300

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #14

2019-05-11 11:27

MOT test number

429988260761

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Rear Brake load sensing valve seized and ABS not fitted or inoperative (1.1.17 (c) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2018-01-23 09:01

MOT test number

471565138446

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Oil leak
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #12

2017-01-30 11:55

MOT test number

164069804660

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #11

2016-01-27 09:47

MOT test number

827429151481

Result

✓ Passed

**MOT #10** 2015-01-19 10:35**MOT test number** 838309715084**Result** ✓ Passed**Notice** Oil leak**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2014-01-20 11:14**MOT test number** 947490124091**Result** ✓ Passed**MOT #8** 2013-01-14 10:57**MOT test number** 737764413000**Result** ✓ Passed**Notice** Rev counter not working**MOT #7** 2012-01-24 11:19**MOT test number** 409594722055**Result** ✓ Passed**MOT #6** 2011-01-28 10:09**MOT test number** 939398321021**Result** ✓ Passed**Notice** Oil leak from engine sump area**Notice** Air bag fault warning lamp illuminated**MOT #5** 2010-02-02 14:04**MOT test number** 184703330450**Result** ✓ Passed



MOT #4	2009-01-28 15:35
MOT test number	634898329099
Result	✓ Passed
MOT #3	2008-02-04 10:51
MOT test number	864505738033
Result	✓ Passed
MOT #2	2007-02-05 11:45
MOT test number	764946537003
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2006-02-02 16:55
MOT test number	660593636099
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-02-11
Last registration	2021-12-22
Complete history	See info



Registration #1	2002-02-11	16 mi
Registration #2	2006-02-02	26.381 mi
Registration #3	2007-02-05	31.686 mi
Registration #4	2008-02-04	37.137 mi
Registration #5	2009-01-28	41.659 mi
Registration #6	2010-02-02	46.175 mi
Registration #7	2011-01-28	50.922 mi
Registration #8	2012-01-24	55.902 mi
Registration #9	2013-01-14	59.450 mi
Registration #10	2014-01-20	63.097 mi
Registration #11	2015-01-19	65.591 mi
Registration #12	2016-01-19	65.591 mi
Registration #13	2017-01-19	65.591 mi
Registration #14	2018-01-19	65.591 mi
Registration #15	2019-01-19	65.591 mi
Registration #16	2020-01-19	65.591 mi
Registration #17	2021-01-19	65.591 mi
Registration #18	2022-01-19	65.591 mi
Registration #19	2023-01-19	65.591 mi
Registration #20	2024-01-19	65.591 mi
Registration #21	2025-01-19	65.591 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2060 mm
Height	1827 mm
Length	3995 mm
Wheel base	2600 mm
Kerb weight	1110 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of axles	2
Engine number	C307444