




report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.6 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	77
Total items failed	5

MOT #23 2023-10-16 10:53

MOT test number 610347446490

Result ✓ Passed

Next expiry date 2024-10-31

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))

Advice Suspension arm pin or bush worn but not resulting in excessive movement Both rear arms, front bushes (5.3.4 (a) (i))

MOT #22 2022-10-06 16:40

MOT test number 241070865849

Result ✓ Passed

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

MOT #21 2022-10-05 15:50

MOT test number 404426754237

Result ✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))



MOT #20 2021-11-01 16:03

MOT test number 120034051873

Result ✔ Passed

MOT #19 2021-10-20 16:22

MOT test number 769724586936

Result ✘ Failed

MAJOR Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

MAJOR Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MAJOR Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #18 2021-10-08 10:25

MOT test number 669525934034

Result ✘ Failed

Advice Coil spring corroded all coil springs corroded (5.3.1 (b) (i))

MAJOR Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill corroded and holed (5.3.6 (a) (i))

Advice Front Inner Brake pad(s) wearing thin brake pads worn low (1.1.13 (a) (ii))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength os sill corroded and holed (5.3.6 (a) (i))

DANGEROUS Offside Rear Wheel bearing play so excessive it is likely to break up wheel bearing has excessive play (5.1.3 (a) (ii))

MOT #17 2020-10-02 12:43

MOT test number 750167573177

Result ✔ Passed

Advice Rear Lower Suspension component pin or bush slightly worn both rear lower shocker bushes worn (5.3.4 (a) (i))



MOT #16 2020-10-01 08:53

MOT test number 706057155053

Result ✗ Failed

MAJOR Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Advice Rear Lower Suspension component pin or bush slightly worn both rear lower shocker bushes worn (5.3.4 (a) (i))

MOT #15 2019-09-30 12:19

MOT test number 959776674392

Result ✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge front tyres wearing on inner edges (5.2.3 (e))

MOT #14 2019-09-30 11:32

MOT test number 297704983199

Result ✗ Failed

Advice Front Tyre worn close to legal limit/worn on edge front tyres wearing on inner edges (5.2.3 (e))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #13 2018-10-04 08:33

MOT test number 136179045330

Result ✓ Passed

Advice Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Play in steering rack inner joint(s)



MOT #12 2018-09-27 12:59

MOT test number 265206500640

Result ✗ Failed

MAJOR Rear Other passenger door cannot be opened from outside the vehicle tailgate (6.2.3 (a))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MAJOR Brake fluid contaminated fluid black (1.8 (a))

Advice Offside Front Play in steering rack inner joint(s)

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Play in steering rack inner joint(s)

MOT #11 2017-09-26 14:12

MOT test number 848662298551

Result ✓ Passed

Advice Vehicle fitted with under body trays obscuring underside from inspection

Advice Front Play in steering rack inner joint(s) both arms

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front Steering system slightly rough strut top bearings (2.2.D.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #10	2017-09-22 11:08
MOT test number	156975754339
Result	✗ Failed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Fail	Nearside Rear rear brake excessively fluctuating (3.7.B.3)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Vehicle fitted with under body trays obscuring underside from inspection
Advice	Offside Front Steering system slightly rough strut top bearings (2.2.D.1)
Advice	Front Play in steering rack inner joint(s) both arms
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #9	2016-09-27 15:06
MOT test number	674734776601
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8	2015-09-28 14:33
MOT test number	962529466232
Result	✓ Passed



MOT #7 2015-05-22 10:00

MOT test number 225112745142

Result ✔ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Engine management light showing on dash
- Notice** Offside front tyre showing signs of sidewall damage but not exposing the cords
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Oil leak
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Nearside front tyre showing signs of outer sidewall damage but not exposing cords
- Notice** Nearside front tyre inner showing signs of seperation
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #6

2015-05-21 16:19

MOT test number

395931345143

Result

✗ Failed

- Notice** Nearside front tyre inner showing signs of seperation
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Engine management light showing on dash
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Offside front tyre showing signs of sidewall damage but not exposing the cords
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Oil leak
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Nearside front tyre showing signs of outer sidewall damage but not exposing cords



MOT #5 2014-05-19 14:13

MOT test number 469979534158

Result ✔ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)
- Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #4 2013-05-13 17:16

MOT test number 435413833169

Result ✔ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2013-05-13 09:51

MOT test number 945063733167

Result ✘ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nail in offside rear tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2012-04-30 09:31

MOT test number 776201822199

Result ✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1 2011-05-12 09:22

MOT test number 745732131155

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
31 October 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BD08ZDK
Plate since	2024-03-29
Current registration	BD08ZDK
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-05-20
Last registration	2023-10-16
Complete history	See info



Registration #1	2008-05-20	8 mi
Registration #2	2011-05-12	25.023 mi
Registration #3	2012-04-30	32.464 mi
Registration #4	2013-05-13	41.411 mi
Registration #5	2013-05-13	41.411 mi
Registration #6	2014-05-19	49.455 mi
Registration #7	2015-05-21	57.436 mi
Registration #8	2015-05-22	57.436 mi
Registration #9	2015-09-28	57.508 mi
Registration #10	2016-09-27	68.034 mi
Registration #11	2017-09-22	78.183 mi
Registration #12	2017-09-26	78.255 mi
Registration #13	2018-09-27	87.370 mi
Registration #14	2019-09-27	96.485 mi
Registration #15	2019-09-27	96.485 mi
Registration #16	2019-09-27	96.485 mi
Registration #17	2019-09-27	96.485 mi
Registration #18	2019-09-27	96.485 mi
Registration #19	2019-09-27	96.485 mi
Registration #20	2019-09-27	96.485 mi
Registration #21	2019-09-27	96.485 mi
Registration #22	2019-09-27	96.485 mi
Registration #23	2019-09-27	96.485 mi
Registration #24	2019-09-27	96.485 mi
Registration #25	2019-09-27	96.485 mi



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1789 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	080122132442BG