





report date: 2024-03-29

General information

Make	FIAT
Model	500 L MULTIJET POP STAR
Colour	Red
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



WP13KDU report date: 2024-03-29

MOT history

MOT expiry date	2025-03-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	17
Total items failed	11

MOT #13		2024-03-28 12:35
MOT test	number	188971312127
Result		✓ Passed
Next expi	ry date	2025-03-27
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2022-10-21 12:56
MOT test	number	921119023811
Result		✓ Passed
Advice	Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii))	
Advice	Glow plug light flashing. offside front seat belt stalk casing missing.	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11 2022-10-18 13:58 596555835382 **MOT** test number Result × Failed Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i)) Fail Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Advice Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii)) **Advice** Glow plug light flashing. offside front seat belt stalk casing missing. both front daytime running lights not working.

 MOT #10
 2021-10-25 10:53

 MOT test number
 950026407083

 Result
 ✓ Passed

 MOT #9
 2021-10-25 10:53

 MOT test number
 657103906308

 Result
 X Failed

 Pass with rectification
 Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Slight movement to offside front strut upper mounting

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

MOT test number

682628589682

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge 225/45/17 (5.2.3 (e))

2018-06-14 07:54 **MOT #5** 251983170073 **MOT** test number Result × Failed Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Offside Front Tyre worn close to legal limit/worn on edge 225/45/17 (5.2.3 (e)) **Advice** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Nearside Front Tyre tread depth below requirements of 1.6mm inner edge 225/45/17 (5.2.3 (e)) Fail **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Nail in tyre inner edge

MOT #4

MOT test number

Result

Advice Parking brake lever has little reserve travel (3.1.6b)

CarCheck.co.uk page 5/13



Result

WP13KDU

report date: 2024-03-29

✓ Passed

MOT test number

129840862453

Result

Advice Offside Front Tyre worn close to the legal limit 225/45/17 (4.1.E.1)

Advice Parking brake lever has little reserve travel (3.1.6b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm outer edge 225/45/17 (4.1.E.1)

 MOT #2
 2016-05-12 16:22

 MOT test number
 288377316779

MOT #1 2016-05-12 16:22

MOT test number 632258275237

Result × Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

WP13KDU

report date: 2024-03-29

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes

See in this check if this FIAT had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-15
Last registration	2024-03-28
Complete history	See info



Registration #1	2013-05-15	7 mi
Registration #2	2016-05-12	42.180 mi
Registration #3	2016-05-12	42.180 mi
Registration #4	2017-05-09	56.633 mi
Registration #5	2017-05-09	56.633 mi
Registration #6	2018-06-14	71.767 mi
Registration #7	2018-06-14	71.771 mi
Registration #8	2019-06-13	76.520 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1315 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 4939234