





General information

Make	ΤΟΥΟΤΑ
Model	CELICA VVTI RED
Colour	Black
Year of manufacture	2004
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I







Internet history	
Entry 1	
Date	2021-09-17
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-02
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	29
Total items failed	18

MOT #23	2024-03-26 13:05
MOT test number	299384624403
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))	
Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))	
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	



MOT #22		2023-04-03 16:19
MOT test	number	613306078532
Result		✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #21	2023-03-22 16:48
MOT test number	283636268439
Result	🗙 Failed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #20	2022-03-08 12:03
MOT test number	339488906662
Result	✓ Passed
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #19	2022-03-04 12:42	
MOT test number	140806441242	
Result	🗙 Failed	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))		
Fail Battery insecure and likely to cause a short circuit (4.13 (a) (ii))		





MOT #18		2021-03-19 16:10
MOT test	number	763571986431
Result		✓ Passed
Advice Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))		
Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))		

MOT #17	2020-03-19 10:41
MOT test number	558586435591
Result	✓ Passed
Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	

MOT #16	2018-12-03 14:31
MOT test number	258851111907
Result	✓ Passed

MOT #15		2017-10-16 14:02
MOT test	number	145095445238
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Under-trays fitted obscuring some components	
Advice	Supplementary Restraint System warning lamp does not illuminate (5.4.2)	



MOT #14	2017-10-02 10:02
MOT test number	539365347360
Result	🗙 Failed
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Headlamp aim too high (1.8)	
Advice Under-trays fitted obscuring some components	

MOT #13	2016-09-27 10:42
MOT test number	380877970308
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #12	2016-09-20 14:47	
MOT test number	538944198667	
Result	× Failed	
Advice Rear Brake pad(s) wearing thin (3.5.1g)		
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Front Brakes imbalanced across an axle (3.7.B.5b)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)		

MOT #11	2015-09-14 11:05
MOT test number	874502752370
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #10	2014-09-02 12:52
MOT test number	275055744254
Result	✓ Passed
МОТ #9	2013-07-16 13:39
MOT test number	299207093470
Result	✓ Passed
MOT #8	2012-06-28 11:41
MOT test number	186460382165
Result	✓ Passed
MOT #7	2011-06-06 16:26
MOT test number	156647351103
Result	✓ Passed
МОТ #6	2011-06-03 12:15
MOT test number	656704351197
Result	🗙 Failed
Fail Offside Front Brake hose seriously damaged (found during steering least)	ock to lock check) (2.2.D.2b)
MOT #5	2010-05-24 13:56
MOT test number	402594840114

MOTILESL	Indinber	402394840114
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2009-05-07 11:14
MOT test number	742057929139
Result	✓ Passed





2008-05-06 14:57
211097928135
✓ Passed
2007-05-03 12:12
144483827175
✓ Passed
2007-05-03 12:12

MOT test number		544693127126
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Advice Nearside Front	Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectification	Offside Headlamp aim too low (1.8)	
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed	Х МОТ
Tax due: 1 April 2025	Expired: 2 April 2024
Tax status	Valid until 1 April
Days left	338
MOT expiry date	2 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 10 200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-04-30
Last registration	2024-03-26
Complete history	<u>See info</u>



Registration #1	2004-04-30	29 mi
Registration #2	2007-05-03	11.992 mi
Registration #3	2008-05-06	19.001 mi
Registration #4	2009-05-07	24.905 mi
Registration #5	2010-05-24	33.246 mi
Registration #6	2011-06-03	38.556 mi
Registration #7	2011-06-06	38.588 mi
Registration #8	2012-06-28	43.508 mi
Registration #9	2013-07-16	48.215 mi
Registration #10	2014-09-02	53.714 mi
Registration #11	2015-09-14	59.489 mi
Registration #12	2016-09-20	64.642 mi
Registration #13		11.117 esi
Registration #14		11.777 esi
Registration #15		10.207 mi
Design and the state		
Registration #16		11.777 mi
Registration #16		11.777 est 11.777 est
-		01,000 est 01,000 est 01,000 est
Registration #17		0.222 es
Registration #17 Registration #18		0.222 es
Registration #17 Registration #18 Registration #19		0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46
Registration #17 Registration #18 Registration #19 Registration #20		0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		0.777 46 0.777 46 0.777 46 0.777 46 0.777 46 0.777 46 0.777 46
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		0.777 46 0.777 46 0.777 46 0.777 46 0.777 46 0.777 46 0.777 46







Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection

Number of doors	3
Number of seats	4
Engine number	1ZZ1939118