



report date: 2024-03-28

## General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-11-29
Pictures	2
Listing price	<a href="#">View report</a>

Buy Now, Pay Later!

The Pause Plan gives you a low-month welcome break from your payments at the start of your agreement, giving you extra breathing space.

THE PAUSE PLAN



AutoTrader

Highly Rated

FOR OUR CUSTOMER SERVICE 2020



source: yesauto.com



MOT history

MOT expiry date	2024-12-30
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	56
Total items failed	1

MOT #162023-12-07 10:37

MOT test number605606044843

Result✓ Passed

Next expiry date2024-12-30

- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceRear Suspension arm corroded but not seriously weakened All (5.3.3 (b) (i))
- AdviceFront Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- AdviceFront Exhaust mounting defective (6.1.2 (a))
- AdviceRear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2023-11-27 16:18

**MOT test number**

106949026731

**Result****✗ Failed****Advice** Rear Suspension arm corroded but not seriously weakened All (5.3.3 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Emissions unable to be completed UNABLE TO REV TO CARRY OUT TEST (8.2.2.2 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed 2055516 (5.2.3 (d) (ii))**Advice** Front Exhaust mounting defective (6.1.2 (a))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #14**

2022-12-21 14:23

**MOT test number**

444980115893

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2022-12-21 11:57**MOT test number** 759008265141**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-12-31 13:23**MOT test number** 954804412203**Result** ✓ Passed**MOT #11** 2021-10-08 15:21**MOT test number** 765900045747**Result** ✓ Passed**Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))**Advice** Engine cover fitted**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))**Advice** Front Exhaust mounting defective exhaust hanger worn thin (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Undertray fitted**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2021-10-07 14:55

**MOT test number**

606868912798

**Result****✗ Failed**

**Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))

**Advice** Engine cover fitted

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Exhaust mounting defective exhaust hanger worn thin (6.1.2 (a))

**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))

**Advice** Undertray fitted

**MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9**

2020-10-05 11:20

**MOT test number**

793887983547

**Result****✓ Passed**

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8**

2020-10-05 11:20

**MOT test number**

777548037633

**Result****✗ Failed**

**Pass with rectification** Rear Direction indicator incorrect colour both rear bulbs (4.4.3 (a))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7** 2019-10-01 09:56**MOT test number** 339135499215**Result** ✓ Passed**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under body of vehicle corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front tyres worn on inner edge. Advise alignment to be checked.**MOT #6** 2018-09-11 14:35**MOT test number** 403344336574**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2017-09-19 09:32**MOT test number** 159349356847**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened slightly lipped (3.5.1i)**MOT #4** 2016-09-28 09:04**MOT test number** 630121506301**Result** ✓ Passed



MOT #3	2015-10-08 10:49
MOT test number	446591446164
Result	✓ Passed
<div><div>Advice</div>Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div> <div><div>Advice</div>Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div>	
MOT #2	2014-09-19 12:23
MOT test number	846042764245
Result	✓ Passed
MOT #1	2013-09-30 09:25
MOT test number	235953873245
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
30 December 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	30 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-07
Last registration	2023-12-07
Complete history	<a href="#">See info</a>



Registration #1	2010-10-07	29 mi
Registration #2	2013-09-30	14.516 mi
Registration #3	2014-09-19	19.792 mi
Registration #4	2015-10-08	25.290 mi
Registration #5	2016-09-28	31.024 mi
Registration #6	2017-09-19	35.736 mi
Registration #7	2018-09-11	45.570 mi
Registration #8	2019-10-01	69.431 mi
Registration #9	2020-10-05	83.087 mi
Registration #10	2021-09-29	95.377 mi
Registration #11	2022-09-29	107.667 mi
Registration #12	2023-09-29	119.957 mi
Registration #13	2024-03-28	132.247 mi
Registration #14	2025-03-28	144.537 mi
Registration #15	2026-03-28	156.827 mi
Registration #16	2027-03-28	169.117 mi
Registration #17	2028-03-28	181.407 mi
Registration #18	2029-03-28	193.697 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602