



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Silver
Year of manufacture	2006
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B





MOT history

MOT expiry date	2025-03-31
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	60
Total items failed	28

MOT #26	2024-03-29 11:38
MOT test number	611172571340
Result	✓ Passed
Next expiry date	2025-03-31
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #25	2023-04-01 17:10
MOT test number	982512180570
Result	✓ Passed

MOT #24	2023-04-01 17:10
MOT test number	823328974808
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #23	2021-12-14 13:15
MOT test number	533652396059
Result	✓ Passed



MOT #22	2020-11-27 16:25
MOT test number	612528244822
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Drivers door handle broken but still able to open

MOT #21	2019-12-11 17:03
MOT test number	704698954310
Result	✓ Passed
Advice	Both front headlamps damaged secured at time of test
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Damage to front bumper secure at time off test

**MOT #20**

2019-11-30 13:37

MOT test number

314065151943

Result

✗ Failed

- Fail** Offside Front Tyre fouling a part of the vehicle Fouling on mudguard (5.2.3 (f))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Minor exhaust blow from rear joint
- Fail** Headlamp insecure Both sides (4.1.1 (c))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Offside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #19

2018-12-20 14:02

MOT test number

227799543064

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18**

2018-12-19 15:50

MOT test number

851099599090

Result**✗ Failed****Advice**

Items removed from driver's view prior to test

Fail

Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Fail

Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Offside Front Position lamp not working (4.2.1 (a))

MOT #17

2017-12-20 17:27

MOT test number

916077030155

Result**✓ Passed****Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Front wheel bearing has slight play (2.5.A.3c)

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Both front discs corroded

Advice

Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both rear (2.4.G.2)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

**MOT #16**

2017-12-20 17:27

MOT test number

381373757365

Result

✗ Failed

Advice Both front discs corroded**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both rear (2.4.G.2)**MOT #15**

2016-10-06 14:49

MOT test number

152115321580

Result

✓ Passed

Advice Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #14**

2016-10-01 11:07

MOT test number

385240566562

Result

✗ Failed

Fail Nearside Front Body has a sharp edge caused by damage wing (6.1.C.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Headlamp insecure (1.7.3)**Advice** Front bumper insecure**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Nearside Headlamp aim too high (1.8)



MOT #13	2015-09-30 16:33
MOT test number	562696179629
Result	✓ Passed
Advice	Child seat fitted not allowing full inspection of adult belt

MOT #12	2014-10-04 10:37
MOT test number	115047174242
Result	✓ Passed
Advice	Nearside Front Direction indicators slightly discoloured (1.4.A.2f)
Notice	Small splits windscreen wiper blade
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	Items removed from driver's view prior to test
Advice	Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2014-10-04 10:37

MOT test number

226027974256

Result**✗ Failed****Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Small splits windscreen wiper blade**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Items removed from driver's view prior to test**Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10**

2013-09-11 16:16

MOT test number

715304053262

Result**✓ Passed****MOT #9**

2013-09-11 09:32

MOT test number

758804453299

Result**✗ Failed****Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #8** 2012-09-24 17:22**MOT test number** 535718362217**Result** ✓ Passed**MOT #7** 2012-09-20 14:42**MOT test number** 578054262201**Result** ✗ Failed**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Notice** Wiper blade split and smeary**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**MOT #6** 2011-09-21 17:00**MOT test number** 655154261263**Result** ✓ Passed**Notice** Child seat fitted to nearside rear seat not allowing full inspection of adult**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Front brake discs worn**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-09-21 17:00**MOT test number** 356094761289**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Front brake discs worn**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted to nearside rear seat not allowing full inspection of adult

**MOT #4** 2010-09-22 09:35**MOT test number** 304465060237**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Nearside rear tyre outer edge starting to wear**MOT #3** 2010-09-22 09:35**MOT test number** 943265160288**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Nearside rear tyre outer edge starting to wear**MOT #2** 2009-04-07 14:27**MOT test number** 700087599069**Result** ✓ Passed**MOT #1** 2009-04-07 09:43**MOT test number** 184067099093**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
31 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-04-25
Last registration	2024-03-29
Complete history	See info



Registration #1	2006-04-25	17 mi
Registration #2	2009-04-07	20.652 mi
Registration #3	2009-04-07	20.652 mi
Registration #4	2010-09-22	30.060 mi
Registration #5	2011-09-21	36.982 mi
Registration #6	2012-09-20	44.846 mi
Registration #7	2012-09-24	44.924 mi
Registration #8	2013-09-11	55.251 mi
Registration #9	2013-09-11	55.251 mi
Registration #10	2014-10-04	60.587 mi
Registration #11	2015-09-30	65.094 mi
Registration #12	2016-10-01	68.868 mi
Registration #13	2016-10-01	68.868 mi
Registration #14	2016-10-01	68.868 mi
Registration #15	2016-10-01	68.868 mi
Registration #16	2016-10-01	68.868 mi
Registration #17	2016-10-01	68.868 mi
Registration #18	2016-10-01	68.868 mi
Registration #19	2016-10-01	68.868 mi
Registration #20	2016-10-01	68.868 mi
Registration #21	2016-10-01	68.868 mi
Registration #22	2016-10-01	68.868 mi
Registration #23	2016-10-01	68.868 mi
Registration #24	2016-10-01	68.868 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	5232018