



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-23
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	19
Total items failed	18

MOT #18	2023-04-19 16:23
---------	------------------

MOT test number	808290970867
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-04-18
------------------	------------

- Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #17**

2023-04-03 13:29

MOT test number

600712811000

Result**✗ Failed****Fail**

Rear Rear fog lamp not working (4.5.1 (a) (ii))

Advice

Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice

Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16

2022-04-19 08:20

MOT test number

132163282550

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2022-04-08 09:46

MOT test number

531332891526

Result

✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Fail** Offside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #14

2021-02-25 17:23

MOT test number

535940740041

Result

✓ Passed

- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13

2019-05-09 15:45

MOT test number

378777302745

Result

✓ Passed

**MOT #12** 2019-05-09 09:23**MOT test number** 601065676258**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2018-05-21 16:33**MOT test number** 288635861205**Result** ✓ Passed**MOT #10** 2017-03-15 10:00**MOT test number** 977881692683**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #9** 2016-03-14 13:13**MOT test number** 555841033770**Result** ✓ Passed**Advice** Offside Front Body has slight corrosion outer sill (6.1.B.2)**MOT #8** 2015-04-14 12:56**MOT test number** 807654205168**Result** ✓ Passed**MOT #7** 2014-04-08 13:06**MOT test number** 116298894031**Result** ✓ Passed

**MOT #6** 2013-03-13 13:29**MOT test number** 979312773015**Result** ✓ Passed**MOT #5** 2013-03-13 12:08**MOT test number** 875202773072**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside fornt tyre is perished/cracked**MOT #4** 2012-03-31 09:19**MOT test number** 998531392016**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2011-04-19 14:09**MOT test number** 197859501159**Result** ✓ Passed**MOT #2** 2010-03-09 11:49**MOT test number** 243528760018**Result** ✓ Passed**MOT #1** 2010-03-09 11:49**MOT test number** 113328760076**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-26
Last registration	2023-04-19
Complete history	See info



Registration #1	2006-10-26	19 mi
Registration #2	2010-03-09	16.151 mi
Registration #3	2011-04-19	19.656 mi
Registration #4	2012-03-31	22.035 mi
Registration #5	2013-03-13	24.195 mi
Registration #6	2013-03-13	24.195 mi
Registration #7	2014-04-08	26.675 mi
Registration #8	2015-04-14	28.648 mi
Registration #9	2016-03-14	32.212 mi
Registration #10	2017-03-15	35.669 mi
Registration #11	2018-03-15	35.669 mi
Registration #12	2019-03-15	35.669 mi
Registration #13	2020-03-15	35.669 mi
Registration #14	2021-03-15	35.669 mi
Registration #15	2022-03-15	35.669 mi
Registration #16	2023-03-15	35.669 mi
Registration #17	2024-03-15	35.669 mi
Registration #18	2025-03-15	35.669 mi
Registration #19	2026-03-15	35.669 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB663111139