



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 2



Date	2021-07-08
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-07
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #15	2023-07-25 14:57
MOT test number	233423656806
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-07-21 13:49
MOT test number	585535862317
Result	✓ Passed

MOT #13	2021-07-27 15:10
MOT test number	489948381923
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2020-11-23 11:22
MOT test number	926072124465
Result	✓ Passed

**MOT #11** 2019-11-09 16:46**MOT test number** 275135573088**Result** ✓ Passed**MOT #10** 2018-11-01 13:51**MOT test number** 654938466366**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #9** 2017-11-06 08:17**MOT test number** 972144137365**Result** ✓ Passed**MOT #8** 2016-11-09 10:56**MOT test number** 837837831237**Result** ✓ Passed

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**MOT #7** 2015-11-09 12:15**MOT test number** 710995475021**Result** ✓ Passed

**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2015-11-09 11:04**MOT test number** 570321269012**Result** ✗ Failed**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2014-11-17 09:28**MOT test number** 378561124357**Result** ✓ Passed**MOT #4** 2014-11-17 09:28**MOT test number** 919481124319**Result** ✗ Failed**Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)**MOT #3** 2013-11-19 11:11**MOT test number** 859563923354**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2012-11-20 09:36**MOT test number** 516295022383**Result** ✓ Passed



MOT #1	2012-11-20 09:36
MOT test number	166535122348
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
26 July 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	26 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-28
Last registration	2023-07-25
Complete history	<a href="#">See info</a>



Registration #1	2009-11-28	10 mi
Registration #2	2012-11-20	10.757 mi
Registration #3	2013-11-19	13.281 mi
Registration #4	2014-11-17	17.086 mi
Registration #5	2015-11-09	21.404 mi
Registration #6	2015-11-09	21.414 mi
Registration #7	2016-11-09	23.920 mi
Registration #8	2017-11-06	25.077 mi
Registration #9	2018-11-06	26.234 mi
Registration #10	2019-11-06	27.391 mi
Registration #11	2020-11-06	28.548 mi
Registration #12	2021-11-06	29.705 mi
Registration #13	2022-11-06	30.862 mi
Registration #14	2023-11-06	32.019 mi
Registration #15	2024-11-06	33.176 mi
Registration #16	2025-11-06	34.333 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	156670
---------------	--------