





### General information

| Make                | MERCEDES-BENZ                   |
|---------------------|---------------------------------|
| Model               | E E220 CDI BLUEEFFICIENCY SPORT |
| Colour              | Red                             |
| Year of manufacture | 2010                            |
| Top speed           | 146 mph                         |
| 0 - 60 mph          | 8.5 seconds                     |
| Gearbox             | 6 speed Manual                  |

## Engine & fuel consumption

| Power                   | 170 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 1.400 rpm |
| Engine capacity         | 2.143 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 41.5 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 142 g/km            |
| CO2 label               | F                   |





## MOT history

| MOT expiry date    | 2021-03-06 |
|--------------------|------------|
| MOT pass rate      | 70 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 3          |
| Total advice items | 16         |
| Total items failed | 4          |

| MOT #10                  |  | 2020-03-07 17:47 |
|--------------------------|--|------------------|
| MOT test I               | number   | 399269764870     |
| Result                   |  | ✓ Passed         |
| Next expiry date 2021-03 |  | 2021-03-06       |
| Advice                   | Steering has slight play in the rack                                     |                  |
| Advice                   | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) |                  |

| МОТ #9          | 2019-02-16 12:14 |
|-----------------|------------------|
| MOT test number | 818554960190     |
| Result          | ✓ Passed         |
|                 |                  |

| МОТ #8          | 2018-02-03 12:53 |
|-----------------|------------------|
| MOT test number | 285725195239     |
| Result          | ✓ Passed         |

| MOT #7          | 2018-02-02 11:30 |
|-----------------|------------------|
| MOT test number | 160577524599     |
| Result          | 🗙 Failed         |
|                 |                  |

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



ROGOCZR report date: 2024-03-29

| MOT #6   |   | 2017-02-01 10:43 |
|----------|---|------------------|
| MOT test | number  | 783019588601     |
| Result   |   | ✓ Passed         |
| Advice   | Rear Brake pad(s) wearing thin (3.5.1g)                                     |                  |
| Advice   | Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |                  |
|          |   |                  |

| MOT #5   | 2015-12-18 16:27 |
|--|------------------|
| MOT test number  | 548489384287     |
| Result   | 🗸 Passed         |
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) |                  |

| MOT #4   | 2015-12-18 16:27   |  |
|--|--|--|
| MOT test number  | 821488582312   |  |
| Result   | × Failed   |  |
| Pass with rectification                                      | Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)  |  |
| Pass with rectification                                      | Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) |  |
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) |  |  |

| MOT #3          | 2014-12-02 18:37 |
|-----------------|------------------|
| MOT test number | 915936634305     |
| Result          | ✓ Passed         |



| MOT #2   |  | 2013-11-11 14:10 |
|----------|--|------------------|
| MOT test | number   | 546585013320     |
| Result   |  | ✓ Passed         |
| Advice   | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |                  |
| Notice   | Under-trays fitted obscuring some underside components                       |                  |
| Notice   | Nail in offside front tyre   |                  |
| Advice   | Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)  |                  |
| Notice   | Offside front tyre worn on edges   |                  |

| MOT #1        |  | 2013-11-11 12:57 |
|---------------|--|------------------|
| MOT test      | number   | 995145413359     |
| Result        |  | 🗙 Failed         |
| <b>Fail</b> N | earside Front Side repeater has less than 50% of the light sources illuminating (1 | .4.A.2c)         |
| Notice        | Nail in offside front tyre   |                  |
| Advice        | Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)        |                  |
| Notice        | Offside front tyre worn on edges   |                  |
| Advice        | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)       |                  |
| Notice        | Under-trays fitted obscuring some underside components                             |                  |



Tax & MOT check

| X<br>Untaxed<br>Tax expired:<br>5 March 2021 | <b>X</b><br><b>MOT</b><br>Expired:<br>6 March 2021 |
|--|--|
| Tax status                                   | Expired at 5 March 2021                            |
| Days left                                    | 1151 days too late                                 |
| MOT expiry date                              | 6 March 2021                                       |
| Full MOT history                             | See MOT history                                    |
| Tax calculation                              |  |

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |                                       |
|----------|---------------------------------------|
| Date     | FERRE                                 |
| Category | A PLANE                               |
| Туре     |                                       |
| Damage 2 | AMPLE                                 |
|          | A A A A A A A A A A A A A A A A A A A |
| Date     | 1. E                                  |
| Category | ant                                   |
| Туре     |                                       |

#### Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| **********   |             |
|--|-------------|
| ********   |             |
|  |             |
| And a second sec |             |
| **********   |             |
| *********  |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this MERCEDES-BENZ had different number plates.   |             |
| Number of plates   |             |
| Carrent registration   |             |
| Plate since  |             |
|  |             |
| Carrient registration  |             |
| Current registration<br>Plate since  |             |





#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 



RO60CZR report date: 2024-03-29

# Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 11              |
| First mileage registration | 2010-11-24      |
| Last registration          | 2020-03-07      |
| Complete history           | <u>See info</u> |



| Registration #1  | 2010-11-24 | 18 mi      |
|------------------|------------|------------|
| Registration #2  | 2013-11-11 | 46.099 mi  |
| Registration #3  | 2013-11-11 | 46.099 mi  |
| Registration #4  | 2014-12-02 | 57.557 mi  |
| Registration #5  | 2015-12-18 | 66.226 mi  |
| Registration #6  | 2015-12-18 | 66.226 mi  |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.117 mi  |

More info  $\rightarrow$ 



### Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| S0482  |                  |
| \$0501 |                  |
| 50566  |                  |
| \$0567 |                  |
| S0569  |                  |

# Dimensions & weight

| Width       | 2028 mm |
|-------------|---------|
| Height      | 1393 mm |
| Length      | 4698 mm |
| Wheel base  | 2760 mm |
| Kerb weight | 1560 kg |

# Additional information

| Fuel tank capacity | 66 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 2                |
| Number of seats    | 4                |
| Number of axles    | 2                |
| Engine number      | 65191130334697   |