





report date: 2024-03-29

### General information

Make	FIAT
Model	DOBLO 16V SX XL MULTIJET
Colour	White
Year of manufacture	2015
Top speed	102 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/11



### Internet history

#### Entry 2

Date 2021-08-01

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-31
Pictures	8
Listing price	View report









source: autotrader.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2024-07-14
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #6	2023-07-05 09:03
MOT test number	669292022169
Result	✓ Passed
Next expiry date	2024-07-14
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view quite a fe (3.2 (a) (i))	w chips and small cracks

MOT #5	2022-07-05 09:00
MOT test number	283285458740
Result	<b>✓</b> Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4		2021-07-14 09:26
MOT test	number	183815270308
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #3 2020-07-15 10:15
MOT test number 664543853196

MOT #2 2019-04-10 11:40

**MOT test number** 206691352756

**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged tread slightly distorted (5.2.3 (d) (ii))

MOT #1 2018-04-06 13:31

MOT test number 196364019070

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	14 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIP PAIS UK
Plate since	mm.m.m
Current registration	NIE AND INC.
Flate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-03-31
Last registration	2023-07-05
Complete history	See info



Registration #1	2015-03-31	11 mi
Registration #2	2018-04-06	28.669 mi
Registration #3	2019-04-10	44.143 mi
Registration #4	2020-07-15	60.394 mi
Registration #5	2021-07-14	71.580 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	2100 mm
Length	4740 mm
Wheel base	3105 mm
Kerb weight	1460 kg
Max. allowed weight	2460 kg

### Additional information

Fuel delivery	Direct Injection	
Number of seats	2	
Number of axles	2	
Engine number Carcheck.co.uk	7236662	page 11/11