





report date: 2024-03-28

General information

Make	MERCEDES-BENZ	
Model	CLA CLA 200 D AMG LINE	
Colour	White	
Year of manufacture	2017	
Top speed	137 mph	
0 - 100 km/h	9.5 seconds	
0 - 60 mph	9.5 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	100 kW / 136 HP / 134 BHP
Max. torque	300 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



FV17AZP

report date: 2024-03-28


Internet history

Entry 1

Date 2021-09-25

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-31
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #7	2023-09-01 10:53	
MOT test number	421563016334	
Result	✓ Passed	
Next expiry date 2024-08-3		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush has slight play (5.3.4 (a) (i)) Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		

MOT #6	2023-08-25 09:34	
MOT test number	516564590832	
Result	X Failed	
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Headlamp aim unable to be tested Off side dip beam is not working (4.1.2 (b))		
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excess Rear bush has slight play (5.3.4 (a) (i))	sive movement	
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		

CarCheck.co.uk page 3/12



FV17AZP

report date: 2024-03-28

MOT test number

Result

Advice

Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

Result

Advice Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #1 2020-05-18 08:41

MOT test number 647167581379

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 10/12



FV17AZP

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-06-05
Last registration	2023-09-01
Complete history	See info



Registration #1	2017-06-05	13 mi
Registration #2	2020-05-18	50.914 mi
Registration #3	2021-05-13	63.297 mi
Registration #4	2021-05-13	63.297 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4640 mm
Wheel base	2699 mm
Kerb weight	1400 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChock co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	65193034013576