





report date: 2024-03-28

General information

| Make | CITROEN |
|---------------------|-------------------|
| Model | C3 PURETECH FLAIR |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 104 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 81 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 109 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-10-02

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



LD18KLK

report date: 2024-03-28

| MOT history | M | OT | history |
|-------------|---|----|---------|
|-------------|---|----|---------|

| MOT expiry date | 2024-07-06 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #4 | 2023-06-27 13:41 |
|------------------|------------------|
| MOT test number | 582862057333 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-06 |

| MOT #3 | 2022-07-07 11:46 |
|----------|--|
| MOT test | number 376410211577 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing cracked on sidewall (5.2.3 (d) (ii)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing cracked on sidewall (5.2.3 (d) (ii)) |

| MOT #2 | 2021-10-06 07:41 |
|-----------------|------------------|
| MOT test number | 605938093438 |
| Result | ✓ Passed |

| MOT #1 | 2021-04-07 09:00 |
|-----------------|------------------|
| MOT test number | 207613757651 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 6 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 4/10



LD18KLK

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| Owner History | |
|---|-------------|
| For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
| | |
| | |
| | |
| *********** | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | UK SIE |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 7/10



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-04-19 |
| Last registration | 2023-06-27 |
| Complete history | See info |



| Registration #1 | 2018-04-19 | 13 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-07 | 11.304 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |


More info >

CarCheck.co.uk page 9/10



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 88% |
| Children | 83% |
| Pedestrian | 59% |
| Safety systems | 58% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| Width | 1829 mm |
|---------------------|---------|
| Height | 1474 mm |
| Length | 3996 mm |
| Wheel base | 2540 mm |
| Kerb weight | 980 kg |
| Max. allowed weight | 1550 kg |

Additional information

| Fuel tank capacity | 50 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B2170399068 |

CarCheck.co.uk page 10/10