



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC AUTHENTIQUE 16V G/SCENIC
Colour	Blue
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-25
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-10-06
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	29
Total items failed	13

MOT #19	2021-10-07 11:34
MOT test number	832488553101
Result	✓ Passed
Next expiry date	2022-10-06
Advice	Central Rear Passenger seat(s) missing at time of test
Minor	Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18	2021-10-05 11:42
MOT test number	555458334965
Result	✗ Failed
Fail	Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
Advice	Central Rear Passenger seat(s) missing at time of test
Minor	Front Headlamp lens slightly defective (4.1.1 (b) (i))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #17**

2020-09-28 15:14

**MOT test number**

536044891554

**Result**

✓ Passed

**Advice**

Registration plate deteriorated but not likely to be misread FRONT AND BACK (0.1 (b))

**Advice**

Front Headlamp has a product on the lens but not seriously reducing light output bothsides (4.1.4 (b))

**Advice**

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #16**

2019-09-30 14:28

**MOT test number**

400324377950

**Result**

✓ Passed

**Advice**

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #15**

2018-01-05 11:58

**MOT test number**

968633206641

**Result**

✓ Passed

**Advice**

Rear x2 seats missing

**Advice**

Registration plate faded but not likely to be misread both front and rear (6.3.1d)

**Advice**

Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #14**

2017-01-05 14:40

**MOT test number**

751948239004

**Result**

✓ Passed

**Advice**

Tyre worn close to the legal limit both front (4.1.E.1)

**Advice**

Sign of minor play n/s front

**MOT #13** 2017-01-05 10:48**MOT test number** 258817279360**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**Fail** Driver's airbag obviously defective (5.4.1)**Advice** Sign of minor play n/s front**MOT #12** 2016-01-06 12:48**MOT test number** 558735629277**Result** ✓ Passed**MOT #11** 2015-12-31 14:07**MOT test number** 471014924567**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick front and rear (3.5.1g)**Fail** Headlamp aim too high and too far to the right. both (1.8)**Fail** Tyre tread depth below requirements of 1.6mm both rear (4.1.E.1)**MOT #10** 2015-01-02 16:49**MOT test number** 495712405094**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-01-02 11:34**MOT test number** 168232805083**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Fail** Headlamp aim too high and too far to the right. (1.8)**MOT #8** 2014-01-03 15:50**MOT test number** 759053204054**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #7** 2013-12-31 13:45**MOT test number** 255875463335**Result** ✗ Failed**Fail** Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #6** 2013-01-05 12:11**MOT test number** 505935503021**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-01-03 10:27**MOT test number** 165193002407**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2010-12-29 10:56**MOT test number** 674303560305**Result** ✓ Passed**MOT #3** 2010-01-04 10:39**MOT test number** 600424800022**Result** ✓ Passed**MOT #2** 2008-11-13 14:43**MOT test number** 873238218307**Result** ✓ Passed**Notice** Nearside front tyre outer sidewall has major damage/wear**Notice** Nearside rear tyre has outer sidewall damage**MOT #1** 2008-11-13 14:43**MOT test number** 163418218329**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Notice** Nearside front tyre outer sidewall has major damage/wear**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Notice** Nearside rear tyre has outer sidewall damage



Tax & MOT check

✕  
Untaxed

Tax expired:  
20 May 2022

✕  
MOT

Expired:  
6 October 2022

Tax status	Expired at 20 May 2022
Days left	710 days too late
MOT expiry date	6 October 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-22
Last registration	2021-10-07
Complete history	<a href="#">See info</a>



Registration #1	2005-12-22	8 mi
Registration #2	2008-11-13	15.412 mi
Registration #3	2010-01-04	21.125 mi
Registration #4	2010-12-29	26.629 mi
Registration #5	2012-01-03	31.431 mi
Registration #6	2013-01-05	35.869 mi
Registration #7	2013-12-31	40.474 mi
Registration #8	2014-01-03	40.474 mi
Registration #9	2015-01-02	45.749 mi
Registration #10	2015-01-02	45.749 mi
Registration #11	2015-01-02	45.749 mi
Registration #12	2015-01-02	45.749 mi
Registration #13	2015-01-02	45.749 mi
Registration #14	2015-01-02	45.749 mi
Registration #15	2015-01-02	45.749 mi
Registration #16	2015-01-02	45.749 mi
Registration #17	2015-01-02	45.749 mi
Registration #18	2015-01-02	45.749 mi
Registration #19	2015-01-02	45.749 mi
Registration #20	2015-01-02	45.749 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1445 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

**Engine number**

D118628