



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CRTD GSI
Colour	Grey
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	191 Nm at 2.500 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN

**MOT history**

MOT #16	2021-12-20 09:57
MOT test number	732005089387
Result	✓ Passed
Next expiry date	2022-12-20
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2021-12-20 09:57
MOT test number	687601884826
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14	2020-11-23 09:38
MOT test number	444342964998
Result	✓ Passed
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge 2.0 (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.1 (5.2.3 (e))

MOT #13	2019-12-16 11:50
MOT test number	851633296023
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2019-12-16 11:50**MOT test number** 304530719211**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-12-20 14:04**MOT test number** 242256813766**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2018-12-20 14:04**MOT test number** 314045422238**Result** ✗ Failed**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2017-12-21 12:57**MOT test number** 992854427769**Result** ✓ Passed**MOT #8** 2017-01-19 14:35**MOT test number** 760844952647**Result** ✓ Passed**MOT #7** 2016-01-14 14:19**MOT test number** 818587437577**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on 1.6mm (4.1.E.1)**MOT #6** 2016-01-14 10:27**MOT test number** 178391890895**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit on 1.6mm (4.1.E.1)**Fail** Front brakes release unevenly (3.7.B.4)**Fail** Front brake application uneven (3.7.B.2)**MOT #5** 2015-01-16 15:52**MOT test number** 455916615055**Result** ✓ Passed**MOT #4** 2014-01-17 16:05**MOT test number** 608257514040**Result** ✓ Passed



MOT #3	2013-01-15 13:14
MOT test number	145125413022
Result	✓ Passed
<div>NoticeRear brake discs slightly worn</div>	

MOT #2	2012-01-24 11:56
MOT test number	298404022070
Result	✓ Passed

MOT #1	2011-01-21 10:43
MOT test number	369671721066
Result	✓ Passed
<div>NoticeBoth front tyres wearing on edges</div>	



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-01-28
Last registration	2021-12-20
Complete history	See info



Registration #1	2008-01-28	19 mi
Registration #2	2011-01-21	20.180 mi
Registration #3	2012-01-24	25.267 mi
Registration #4	2013-01-15	30.622 mi
Registration #5	2014-01-17	34.971 mi
Registration #6	2015-01-16	40.381 mi
Registration #7	2016-01-14	45.399 mi
Registration #8	2016-01-14	45.399 mi
Registration #9	2017-01-19	48.782 mi
Registration #10	2018-01-20	51.277 mi
Registration #11	2018-01-20	51.277 mi
Registration #12	2018-01-20	51.277 mi
Registration #13	2018-01-20	51.277 mi
Registration #14	2018-01-20	51.277 mi
Registration #15	2018-01-20	51.277 mi
Registration #16	2018-01-20	51.277 mi
Registration #17	2018-01-20	51.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1500 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1204 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA8U514149