



report date: 2024-03-29

General information

Make	SUZUKI
Model	GRAND VITARA 16V SE
Colour	Silver
Year of manufacture	2004
Top speed	88 mph
0 - 60 mph	15.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	92 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.590 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	36.7 mpg
Consumption combined	30.7 mpg
CO2 emission	220 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-14
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-25
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	91
Total items failed	7

MOT #23	2023-05-24 09:46
MOT test number	657192717935
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Corrosion starting to form around offside rear body to chassis mounting
Advice	Offside rear tyre worn to wear indicator bars
Advice	Engine has oil leak from rear

**MOT #22**

2023-05-22 10:21

MOT test number

248957506703

Result**✗ Failed**

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front brake pads worn low
- Advice** Engine coolant tank empty
- Advice** Offside front tyre perishing and wearing low in places
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Corrosion starting to form around offside rear body to chassis mounting
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front brake pads worn low
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Brake fluid on min line
- Advice** Nearside front tyre worn smooth and to limit on outer tread band
- Advice** Offside rear tyre worn to wear indicator bars
- Fail** Exhaust has a major leak of exhaust gases centre joint leaking to excess (6.1.2 (a))
- Advice** Engine has oil leak from rear

MOT #21

2022-05-17 15:41

MOT test number

149494840410

Result**✓ Passed**

- Advice** Slight play in nearside front wheel bearing
- Advice** Oil leak, but not excessive Various engine oil leaks (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn smooth on the outer shoulder / tread band area. (5.2.3 (e))
- Advice** Oil leak, but not excessive Transfer box front output shaft seal is leaking (8.4.1 (a) (i))

**MOT #20**

2022-05-17 11:59

MOT test number

541544619900

Result**✗ Failed****Advice** Wheel bearing has slight play Slight play in both front wheel bearings (5.1.3 (a) (i))**Advice** Oil leak, but not excessive Various engine oil leaks (8.4.1 (a) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split around drive shaft (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive Transfer box front output shaft seal is leaking (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn smooth on the outer shoulder / tread band area. (5.2.3 (e))**MOT #19**

2021-05-18 14:33

MOT test number

531277935341

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #18**

2021-05-18 14:33

MOT test number

959416423571

Result**✗ Failed****Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #17**

2020-05-26 14:34

MOT test number

970723910895

Result

✓ Passed

- Advice** Coolant leak
- Advice** Rear tyres perishing
- Advice** Brake pipes corroding
- Advice** Headlamp lenses discolouring
- Advice** Exhaust deteriorating
- Advice** Chassis sections corroding

MOT #16

2020-05-26 08:34

MOT test number

662693401010

Result

✗ Failed

- Advice** Exhaust deteriorating
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Chassis sections corroding
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear tyres perishing
- Advice** Coolant leak
- Advice** Brake pipes corroding
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Headlamp lenses discolouring

**MOT #15**

2019-05-28 13:43

MOT test number

271973275751

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust deteriorating
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Headlamp lenses discolouring

MOT #14

2018-05-30 11:26

MOT test number

627579175544

Result

✓ Passed

- Advice** Chassis sections corroding
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** N/s/f brake slight bind
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pipes corroding
- Advice** Exhaust deteriorating

**MOT #13**

2018-05-30 08:35

MOT test number

403954236158

Result**✗ Failed**

- Advice** Chassis sections corroding
- Advice** Brake pipes corroding
- Advice** Advice fuel filter replacement
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Exhaust deteriorating
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Washer jets half blocked
- Advice** N/s/f brake slight bind
- Advice** Headlamp lenses discolouring
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2017-05-25 10:50

MOT test number

219862214900

Result**✓ Passed**

- Advice** Front driveshaft gaitors deteriorating
- Advice** Exhaust deteriorating
- Advice** Oil leak

**MOT #11**

2016-05-27 08:05

MOT test number

257628228512

Result

✓ Passed

- Advice** Oil leak
- Advice** Chassis sections corroding
- Advice** Headlamp lenses discolouring
- Advice** Exhaust deteriorating

MOT #10

2015-05-29 09:12

MOT test number

579849445146

Result

✓ Passed

- Notice** Rear wiper blade split
- Notice** Chassis sections corroding
- Notice** Exhaust deteriorating
- Notice** Headlamp lenses discolouring
- Notice** Oil leak
- Notice** Damage to rear bumper

MOT #9

2014-05-30 16:35

MOT test number

779780354170

Result

✓ Passed

- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Slight oil leak?

**MOT #8** 2014-05-30 11:11**MOT test number** 355720254151**Result** ✗ Failed**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Slight oil leak?**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2013-05-28 10:35**MOT test number** 575068843150**Result** ✓ Passed**Notice** Chassis sections corroding**Notice** Front brake discs worn**Notice** Oil leak ?**Notice** O/s/f outer cv boot perished small split**MOT #6** 2012-05-23 10:22**MOT test number** 499044542135**Result** ✓ Passed**Notice** Oil leak ?**Notice** O/s/f outer cv boot perishing**MOT #5** 2011-05-11 09:21**MOT test number** 889051531194**Result** ✓ Passed**Notice** Oil leak ?**Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)



MOT #4 2010-05-19 15:33

MOT test number 201219530445

Result ✓ Passed

Notice Exhaust starting to corrode

Notice Slight play in both front wheel bearings

MOT #3 2009-05-14 10:54

MOT test number 152304939136

Result ✓ Passed

MOT #2 2008-05-15 09:23

MOT test number 802956438159

Result ✓ Passed

Notice Rear brakes squealing

Notice Exhaust slightly corroded

MOT #1 2007-05-16 14:35

MOT test number 550716537177

Result ✓ Passed

Notice Small hole in offside outer drive shaft gaiter. â€ â€ plastic sill covers fitted.



Tax & MOT check

X

Untaxed

Tax expired:
9 April 2024

✓

MOT

Expires:
25 May 2024

Tax status	Expired at 9 April 2024
Days left	19 days too late
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-05-19
Last registration	2023-05-24
Complete history	See info



Registration #1	2004-05-19	14 mi
Registration #2	2007-05-16	28.502 mi
Registration #3	2008-05-15	34.389 mi
Registration #4	2009-05-14	39.920 mi
Registration #5	2010-05-19	46.178 mi
Registration #6	2011-05-11	51.745 mi
Registration #7	2012-05-23	57.255 mi
Registration #8	2013-05-28	60.525 mi
Registration #9	2014-05-30	65.066 mi
Registration #10	2014-05-30	65.066 mi
Registration #11	2015-05-29	65.808 mi
Registration #12	2016-05-27	68.737 mi
Registration #13	2017-05-25	72.175 mi
Registration #14	2018-05-23	75.113 mi
Registration #15	2019-05-21	78.051 mi
Registration #16	2020-05-19	80.989 mi
Registration #17	2021-05-17	83.927 mi
Registration #18	2022-05-15	86.865 mi
Registration #19	2023-05-13	89.803 mi
Registration #20	2024-05-11	92.741 mi
Registration #21	2025-05-09	95.679 mi
Registration #22	2026-05-07	98.617 mi
Registration #23	2027-05-05	101.555 mi
Registration #24	2028-05-03	104.493 mi
Registration #25	2029-05-01	107.431 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1740 mm
Length	4215 mm
Wheel base	2480 mm
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G16B-680098